ear install Plane No Cleaned/ PFN THE DMB Id Panel No Air test Blocked Missing wires Missing wires Prepped straws confirmed epoxy MISSMO Mn080 Repairs gas leak fest v pass Prep finished v DMB connector holes cleared " ear flooded Missing Straw: 4 (Scanned twice after Kapton-dots: 94, 95 (cleaning HC wire) HV issues High current wires: 1, 3, 19, 49, 89 FEST HVV Gain epoxy in Dmis connicleured **Notes**