
(a) Fatigue level
p = 0.035
Commanded speed (deg/s)
0
5
10
15
20
25
30
Low
Medium
High
(b) Attention
p = 0.272
Focused
Uncertain
Distracted
(c) Hand-tool distance (m)
p < 0.001
≤0.15
0.15-0.25
0.25-0.35
>0.35