


$$f = 100 \text{ Hz}$$

$$1 \text{ box} = 0.2 \text{ V y-axis}$$

$$1 \text{ box} = 1 \text{ ms x-axis}$$

$$T = 10 \text{ ms}$$

$$V = 5 \text{ V}$$




$$f = 100 \text{ Hz}$$

$$T = 10 \text{ ms}$$

$$V = 5 \text{ V}$$

1 box = 0.5 V y-axis

1 box = 1 ms x-axis



$$f = 100 \text{ Hz}$$

$$T = 10 \text{ ms}$$

$$V = 5 \text{ V}$$

$$1 \text{ box} = 1 \text{ V y-axis}$$

$$1 \text{ box} = 1 \text{ ms x-axis}$$

