

EMAIL ARCHIVE · MAINTENANCE THREAD

Exported: 25/06/2024

=====
From: r.sharma@plant.example.com
To: maintenance@plant.example.com
CC: engineer@plant.example.com
Date: 12/06/2024 09:14
Subject: RE: P-101 Recurring Seal Failure

Team,

Following up on the P-101 issue. We've now had 3 seal failures in 6 months.
The mechanical seal on P-101 failed again last night around 22:30.

Root cause analysis suggests the seal material (VITON) may not be compatible
with the new process fluid introduced in March 2024 (pH < 3.5).

Recommendation: Switch to PTFE seal material. Cost: ~\$450. Lead time: 2 weeks.

Action items:

- Raise work order for P-101 seal replacement using PTFE
- Review fluid compatibility across all pumps in the P-100 series
- Update SOP to specify PTFE seal material

Regards,
R. Sharma (Process Engineer)

=====
From: engineer@plant.example.com
To: maintenance@plant.example.com
Date: 12/06/2024 11:02
Subject: RE: P-101 Recurring Seal Failure

Approved. Please raise PO for PTFE seals.
Also check P-102 · same service, same risk.

Equipment referenced: P-101, P-102, HV-204