Time: 09.13



No : asdaf

DATE: 2020-06-09

LOCATION: KEEMK

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO :SIRL1234567

20G2

SEAL -

DEST KERNA

SHIPPING LINE : CMA CGM KENYA LTD

VESSEL: 090002

TRANSPORTER : LOIJR

DRIVER : asdaf


PARTY DELIVERING CONTAINER : LOIJR

 $B\L NO: asdaf$

VOY NO:OIJDOI

TRUCK NO: LKOIJOERIJ

DELIVERY NOTE:



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair Qty	Hours Labour Cost\$	Material Cost Total Cost
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
			192

Prepared by: boxback admin

Repair Estimated by: boxback admin

Distribution: 1, Transporter: 2, Shpg Line 3 BBL

