

WHITEPAPER

Why all failures are preventable

Reading the warning signs before the plant stops.

THE PREMISE

Machines do not fail without warning. The warning is written in vibration, heat, ultrasound and oil long before a breakdown stops production.

THE FOUR SIGNATURES

- Vibration: imbalance, misalignment and bearing wear appear early
- Heat: loose connections and friction show on thermal images
- Ultrasound: leaks and early bearing faults are audible first
- Oil: wear metals and contamination reveal internal condition

THE PAYOFF

Catch the signature early and every failure becomes a planned, costed intervention instead of an emergency. That is the ARS standard.