



MSCC-Core Change Log

NOTES:

The change log updates are in descending order (newest first). Review all change log date entries before proceeding with the newest update to ensure critical updates have not been missed.

02/20/2018 (Version 119.020)

Changes:



MSCC-Core Change Log

12/04/2018 (Version 119.013)

Changes:

- This release is a major update to MSCC-Core. Please review the MSCC-Core Operators guide for new and updated features.
- MSCC-Core is now completely self configuring. With new installations (the transceiver has never been attached to the PC, MSCC-Core will present a window at start up asking for the PCB version of the transceiver. Default values are set for all parameters including power output, frequency calibration and transmit I/Q balance.
- The firmware of the transceiver **MUST BE UPDATED** to the version included with the release package. This does not apply to transceivers purchased after the date of this release. **Do this first before starting MSCC-Core.**
- An output power calibration may be required after installing this release. The output power management routines have been re-written. Upon the first start this version of MSCC-Core, the transceiver will be updated with default output power values. The default values should be sufficient for the transceiver but they may not be optimal. Check the power output using the MSCC-Core Power-Cal tab.

Known Issues:

- When pressing the tune button, OVER DRIVEN may be momentarily displayed. The transceiver is not being over driven. This will be addressed in a subsequent release.
- When clicking and rotating through the operating modes, OVER DRIVEN may be momentarily displayed.. This will be addressed in a subsequent release.

Defects Corrected:

- The frequency calibration routine(s) were not always setting the PPM value correctly. This has been fixed.



MSCC-Core Change Log

Updated Versions:

- Release Package: 119.013
- MSCC: 119.013
- MS-sdr: Updated
- SDRcore-trans: Updated
- SDRcore-recv: Updated



MSCC-Core Change Log

10/01/2018

Changes:

- Support for the Hardrock 50 has been added.
- Manually uninstalling the previous version of MSCC-Core is no longer required.
- The panadapter has been completely revised.
- CW Pitch control has been added.
- Windows 7 is now supported.

Known Issues:

- The transceiver will occasionally not go into CW mode. The work around is to cycle through the modes and back to CW mode. This normally corrects the issue.
- When changing the mode to AM or clicking through AM, the OVER DRIVE indicator may flash on for a few moments.
- Occasionally MSCC-Core hangs for a few moments before closing. This causes ms-sdr to report "I'm alive" message failure. Click OK on the pop up and all processes will stop.

Defects Corrected:

- If current mode is CW and MSCC-Core is restarted, the internal frequency of the transceiver is not set correctly. This defect has been fixed.
-

Updated Versions:

- Release Package: 118.100
- MSCC: 118.100
- MS-sdr: Updated
- SDRcore-trans: Updated
- SDRcore-recv: Updated



MSCC-Core Change Log

09/01/2018

Changes:

- There is now a BACKUP button on the Misc tab. Clicking this button causes MISC-Core to create a backup of all the initialization and log files.
- There is now a ZIP LOG FILES button on the Misc tab. Clicking the button will create a zip file of all the initialization and log files. The zip file is named "ziplog.zip" and is located in the release-package directory.
- A noise blanker has been implemented. Please refer to the MISC-Core Users Guide for more information.
- Comm port activation of PTT is now supported.
- A name is no longer required when creating a new favorite.
- The Panadapter now has spectrum averaging.
- Added 30MHz to the Frequency Calibration selection list.

Known Issues:

- The transceiver will occasionally not go into CW mode. The work around is to cycle through the modes and back to CW mode. This normally corrects the issue.
- If the current mode is CW and MISC-Core is restarted, the internal frequency of the transceiver is not set correctly. The work around is to cycle through the modes and back to CW. This corrects the issue.
- When changing the mode to AM or clicking through AM, the OVER DRIVE indicator may flash on for a few moments.

Defects Corrected:

- When leaving the I/Q calibration page, MISC-Core was incorrectly issuing a warning pop. This has been corrected.
- MISC-Core now detects when the Multus_msc.ini is missing and correctly presents an error message and terminates.
- MISC-Core now detects if the subsystem has started properly. If not, it presents an error message and terminates.
- MS-sdr was erroneously reporting compression messages to the log. This has been corrected.
- Corrected issue on Win 7 systems. Com port write operations would fail. This has been fixed.



MSCC-Core Change Log

Updated Versions:

- Release Package: 118.090
- MSCC: 118.090
- MS-sdr: Updated
- SDRcore-trans: Updated
- SDRcore-recv: Updated



MSCC-Core Change Log

08/01/2018

Changes:

- This release requires the removal of all initialization files. Navigate to the release package directory and click (or double click) on ini-delete. This program will delete all initialization files. Run MSCC-Initialize after deleting the initialization files.
- The panadapter now displays the current operating mode.
- MSCC-Core now remembers the current screen position for the main display, s-meter display and panadapter display.
- The S-meter now switches to VU in transmit mode.
- Frequency calibration now displays a progress bar when in calibration mode.
- The standard carrier frequency is now a list box.
- The Favs tab has been completely revised. See the MSCC-Core Operators Guide for more information.
- The name of the installation file is now mscc-install.exe
- MSCC-Core now displays the version of all cooperating programs.
- Changing the main frequency may now be accomplished by hover the mouse pointer to a position just above or below the frequency digit and clicking the mouse.
- Transmit audio compression is now available.

Known Issues:

- The transceiver will occasionally not go into CW mode. The work around is to cycle through the modes and back to CW mode. This normally corrects the issue.
- If the current mode is CW and MSCC-Core is restarted, the internal frequency of the transceiver is not set correctly. The work around is to cycle through the modes and back to CW. This corrects the issue.
- When changing the mode to AM or clicking through AM, the OVER DRIVE indicator may flash on for a few moments.

Defects Corrected:

- MSCC/MS-SDR: The main frequency display now displays the correct frequency when MS-SDR detects a frequency change set by the comm port.
- MSCC: Panadapter: The panadapter now displays the correct frequencies on the X axis.
- Incorrect UDP ports were assigned when the Multus_mscci.ini file was updated by MSCC-Core.



MSCC-Core Change Log

Updated Versions:

- Release Package: 118.080
- MSCC: 118.080
- MS-sdr: Updated
- SDRcore-trans: Updated
- SDRcore-recv: Updated



MSCC-Core Change Log

07/13/2018

Changes:

- New Release. This is a major refresh update to MSCC-Core and all companion applications. If MSCC-Core has been previously installed, uninstall it using the Windows uninstall facility. This release requires the removal of all initialization files. Navigate to the release package directory and click (or double click) on ini-delete. This program will delete all initialization files.
- *The transceiver firmware must be upgraded to the version in the release package.*

Known Issues:

- The transceiver will occasionally not go into CW mode. The work around is to cycle through the modes and back to CW mode. This normally corrects the issue.
- If the current mode is CW and MSCC-Core is restarted, the internal frequency of the transceiver is not set correctly. The work around is to cycle through the modes and back to CW. This corrects the issue.

Defects Corrected:

- New release. Multiple defects corrected.

Updated Versions:

- The version of MSCC-Core and all companion applications has been updated.