



ALDILA Composite Products Co.,LTD	APPROVE	CHECK	DESIGN	TITLE	I/O PLC	DATE	08/12/25
			TRƯƠNG ĐÌNH HÀO			DWG No	01
						CODE	



Operating Cycle

1. Enter the product code into the Computer. The Computer sends a signal for the PLC to run in auto mode.
2. Place two Fingers on the to sensor, when X0 X1 X6 X7 are ON, Y2 turns ON to activate the shaft-clamping valve.
3. When X2 X3 are ON, Y4 turns ON to Belt down.
4.When X2 X3 X10 X11 are ON, Y0 Y1 ON, the Motor starts winding.
5. Motor winding cycle completed X2 X3 are ON, Y4 turns OFF to Belt Up.
6. when X6 X7 are ON, Y2 OFF, Y3 ON to release the clamp.
7. Cycle completion and nex step.

ALDILA Composite Products Co.,LTD	APPROVE	CHECK	DESIGN	TITLE	Operating Cycle	DATE	08/12/25
			TRƯƠNG ĐÌNH HÀO			DWG No	02
						CODE	