

N.J.B.A. Newsletter

NJBA Volume 6, Issue 4 02/02/02 Spring is coming soon!

Hi all! So far winter this has not been too harsh, so lets think that spring is coming soon. Things are "sort of" back to "normal" here in the NYC area. Life must go on, people must work, children will play and we all must do what we have to survive. What will still hurt some will be economic losses. Between the WTC, Enron and Ford the country and this area have taken some big hits. Hopefully we can all miss the effects of these and recover quickly to take care of ourselves and our families.

We have a few meets coming up that are a new concept for us. I hope that a lot of you can make

time to get to them.

On February 9th we have a meet at The Blacksmith of Trenton Shop featuring an Iron Pour (Note: There are rain dates for this event).

On March 16th & 17 there is a joint meet with Furnace Town Blacksmith's Guild in Snow Hill Md. Scott Lankton will be the demonstrator on Saturday and run a limited person workshop on Sunday.


On April 13th, at Tim Millers Shop in Bayport, Long Island we have a meet featuring Jona-

than Nedbor as demonstrator.

In May we are hoping to a meet at Greg Phillips shop in Orange Co., N.Y. featuring Bill Senseny of Massachusetts as a guest Demonstrator, there may slots available for a hands on workshop

the next day

These meets are out of the way for a lot of us, but I hope a lot of us can find the time to travel and get out to these meets. People who live near these areas



Bringing in a demonstrator is new to us at NJBA and it is an excellent way to learn new skills and get fresh ideas from an experienced smith. I myself have learned a lot this way and highly recommend making these meets. I am not always thrilled with the trip to some meets I have attended over the years, but I find the experience has been worth every mile.

So start the new year out with some new information and skills learned from watching experienced demonstrators, all four of these meets are

worth the travel time!

Upcoming events for 2002

Remember most of our meets have a <u>"Iron in the Hat"</u> drawing, be sure to bring something.

February 9, with rain dates of the 10th, 16th and 17th at 10am; Meet at Alex Parubchenko's shop in Trenton, NJ. Details and directions on this page 3.

March 16th & 17th; Joint meet with Furnace Town Blacksmith's Guild in Snow Hill Md. Scott Lankton will be the demonstrator on Saturday and run a limited person workshop on Sunday. Details on page.

April 13th: Meet at Tim Millers Shop in Bayport, Long Island featuring Jonathan Nedbor as demon-

strator. Details and directions on page.

May: Possible meet at Greg Phillips shop in Orange Co., N.Y. featuring Bill Senseny of Massachusetts as a guest Demonstrator, Details and directions on page 4.

June - Cold Springs Village, Dates and information to follow part population

tion to follow next newsletter.

July - Monmouth County Fair, Dates and information to follow next newsletter.



Can anyone help a fellow member?

Hello, my name is Eric Cuper and I will be returning to central New Jersey around June 2002 after receiving my MFA in blacksmithing from SIUC. I will be looking for work (in metals) or a studio space, suitable for coal and gas forges as well as a power hammer. I would be interested in a shared larger shop with individuals combining resources and the possibility of allowing access to part timers or teaching situations. I am willing to locate in NJ, eastern PA, or southern NY. I have also recently purchased a 275# air hammer

Rather than use room in the newslet-

All correspondence between ABANA and NJBA is now being posted

with a large compressor and I will be seeking storage for these If I cannot find a studio soon enough. I will gladly pay for space but I am also willing to trade for time on this big hammer when it is functioning. As you can see, I am currently open to many possibilities. Please feel free to contact me with any ideas, suggestions, or inquiries. Eric Cuper, 331 Contentment Rd., IL 62958, 618-351-1391, ericuper@msn.com.

The NJBA Web Site!

The NJBA Web Site is up and running at:

http://njba.abana-chapter.com/

Bruces' links to the ABANA site:

http://www.monmouth.com/~freeman/NJBA/ abanawebsite.htm

NJBA Board of Directors

Marshall Bienstock, June, 2003 663 Casino Dr., Howell, NJ 07731 732-938-6577 732-780-0871 mbienstock@worldnet.att.net **Larry Brown**. Editor, June, 2003 90 William Ave., Staten Island, NY 10308 718-967-4776 lp.brown@verizon.net, brownln@hotmail.com **John Chobrda**, June 2002 231 Morrison Ave., Hightstown NJ 8520 609-443-3106 609-396-9583 JChob@earthlink.net **Bruce Freeman**, June, 2002

222 Laurel Place, Neptune, NJ 07753 732-922-8408, 609-716-2827 freeman@monmouth.com,

freemab@pt.fdah.com Jon Folk, June, 2003 P.O.Box 143, Old Bethpage, NY 11804 516-625-5667. folkforge@worldnet.att.net Bruce Hay, Jr, June 2003

50 Pine St., Lincroft N.J. 7738 732-747-4758

Anton Holstrom, June 2002 26 Saddle Shop rd., Ringoes N.J. 08551-1510 609-446-0349 antonholdstrom@msn.com

Adam R. Howard, June 2003 c/o HHM, P.O. Box 5005, Clinton NJ 08809 908-735-4573 kunstschmeide@aol.com Josh Kavett, June, 2003 471 Casino Dr., Farmingdale, NJ 07727 732-431-21 52, jakavett@aol.com David Macauley, Director June, 2002 4 Patricia Ct., Howell, NJ 07731 732-206-1568, 732-949-8422 drmacauley@att.com, drmacauley@monmouth.com Jeff Morelli, June 2003 234 Rahilly Road, Wrightstown, NJ 08562 609-723-5990 Nate Pettengill, June, 2003 212 Hazel St, 2nd Floor, Rear. Delanco, NJ 08075 nate.pettengill@lmco.com Greg Phillips, June 2002 (845) 457-5671, Acorn Forge, 937 Route 17k, Montgomery, NY 12549 suresign@frontiernet.net Steven W. Rhoades, June, 2003 513 Harding Highway, Vineland, NJ 08360

856-697-4144, hotiron1@juno.com **Bruce Ringier**, June, 2003 346 Rt.565 Wantage, NJ 07641 201-652-4526 wlkngb@yahoo.com Tim Suter, June, 2002 1112 Ladner Ave., Gibbstown, NJ 08027 856-423-4417

February Meet at Alex Parubchenko's

Shop In Trenton


On Feb. 9th with a rain dates of the 10th, 16th and the 17th. This is because the demo is out side and cannot be done in the rain. Alex Parubchenko, the Blacksmith of Trenton, will demonstrate melting steel in a cupola furnace (a continuous melting furnace). He'll do a pour, and, with luck, we'll have a chance to see the result.

Marshall Bienstock will be showing the products of his latest classes (in January) at J.C. Campbell Folk School, and may demonstrate some of the techniques involved. A lunch will be provided by NJBA. Tailgating is permitted, but the shop is NOT in a good area, so you might want to keep things locked up. Attendees are requested to bring a contribution to the IITH.

Directions;

To Alex Parubchenko's shop in Trenton, NJ

Directions: You can get to 334 N. Olden Ave., Trenton, from US Route 1 (Trenton Freeway) or from Interstate Route 295 or via Arena Drive from Interstate Route 195. From US 1, go SE about 1/2 mile to the shop. From I 295, go NW about 2 miles to the shop. From I 295 go NW about 2 miles, where Arena joins Olden, and then about 2 miles NW on Olden to the shop. The shop is at 334 N. Olden Ave. There is a vacant lot next door where you can park. (Phone: 609-396-9583)



March Meet at Furnace Town in Snow Hill, MD

A joint meet will be held with the Furnace Town Blacksmith's Guild in Snow Hill Md. Scott Lankton will be the demonstrator on Saturday and run a limited person workshop on Sunday. Registration is \$20 before the 28th of February and \$25 afterwards. This includes coffee, doughnuts and lunch. There is a buffet dinner on Saturday night for \$15, pre-registration for it is required.

To register contact Mark Williams (Home # 410-632-0914, Work# 410-651-6431, E-mail m_and_mwilliams@juno.com).

The next day's workshop is limited to 12 people and NJBA has two slots reserved, if interested contact Ray Noble as soon as possible (Home # 410-651-0987, Work # 800-220-3015, E-mail nobler511@aol. com)

April 13th Meet at Tim Millers Shop in

Bayport, Long Island

Tim Miller is hosting a meet at his shop in Bayport Long Island, NY. on the 13th of April and it will feature Johnathan Nedbor as Demonstrator. Jonathan is an experienced teacher, demonstrator and Current President of the Northeast Blacksmiths. I have know Jonathan for quite a few years and have seen him demonstrate and he is informative, experienced and answers questions well.

Directions:

To Tim Miller's shop in Bayport, L.I., N.Y.; Take the Long Island Expressway to exit 62 - Nicolls Rd, go south to the end and make a right onto Montauk Highway. Go three lights (quick), look for sign on left, Tim Miller Blacksmith. Go to back of driveway and park on the blacktop before the chain link fence, some tailgaters may be able to park near the shop, call first to make arrangements.

Shop; (631) 419-1185 Cell; (631) 220- 6840

Possible May Meet at Greg Phillips in Orange County, NY

Greg Phillips has set up a meet at his place with Bill Senseney on March 16 & 17. Bill is now focusing on an Art Nouveau style of forging and will do a demo/workshop to that effect. The demonstration will be on Saturday and a workshop limited to several people the next day. The workshop would be for a fee and would be on a first check, first reservation basis.

For information concerning the meet and workshop contact:

Greg Phillips, (845) 457-5671, Acorn Forge, 937 Route 17k, Montgomery, NY 12549 gphillips@hvc.rr.com

Directions to Greg Phillips Shop
From NJ: Take the Garden State Parkway
north into New York State. Pick up the NYS Thruway
(Route 87), and take it north to exit 17 (NewburghStewart Airport) after exiting and the toll booth DO
NOT bear right onto Route 84, continue straight to
traffic light at Route 17k. Turn right (west) onto
Route 17k proceed about 9 mi to 937 Rt. 17k (Greg's
house) it will be on the left, there is a sign in front of
the house "A Sure Sign". The building behind the
house has the second floor painted with rainbow colors. (For anyone that has been to the Orange County
Farmers Museum the house is less than a mile past the
sign for the museum.)

Report on the November Meet at Peters Valley

On November 18th, 2001 NJBA had a meet at Peters Valley Craft Center. We had a turn out of about 15 people. The meets demonstration was provided by, Maegan Crowley, the resident smith at Peters Valley. We started with a tour of the Centers teaching Blacksmith shop area, discussing up coming

plans for the shop. We then proceeded to Maegans' shop where she showed various items in the shop that were either completed or in progress.

The demonstration started with Maegan making three dimensional shapes by forging a thin plate through a cut out area in a steel plate. She had various shapes in the shop and for the demonstration she used a plate with two different size hexagons. She makes a striking tool from the cut out piece of the plate, which she uses to start and define the shape she is making in the form. She then uses a striking tool that is the same shape but has a hollow three dimensional shape dished up to push the metal down into the form. After that she defines and textures the piece with various shaped striking tolls and hammers. The geometric shapes formed by these are interesting and have a lot of possibilities the technique may be applied to various projects. After lunch and iron in the hat we continued the demonstration in the teaching shop using a gas forge and the power hammer to form a two legged shape out of pipe and a larger diameter piece of tubing to form a three legged sculpture. We would like to thank Maegan for her time and efforts involved in setting this up and demonstrating. The meet was informative and successful and hopefully Peters Valley invites us back again in the future.



December Holiday Party

On December 9th NJBA had its annual holiday party. The party was once again hosted in the home of Marshall and Jan Bienstock. Marshall's home is a great log cabin style home which does a good job of showing off his ironwork collection.

Marshall has many of his own pieces and projects on display as well as many old and antique pieces he has acquired over the years. About twelve members were in attendance and a good time was had by all.

NJBA would like to once again thank Marshall and Jan for the great job done hosting the party.

Blacksmithing

Workshops and Classes:

Peters Valley Craft Education Center

19 Kuhn Rd., Layton, NJ 07851 (973)948-5200 pv@warwick.net www.pvcrafts.org

Academy of Traditional Arts Carrol County Farm Museum

500 South Center St. Westminster, MD 21157 (410)848-7775 (410)876-2667

Touchstone Center for Crafts

R.D.#1, Box 60, Farmington, PA 15437 (724)329-1370 Fax: (724)329-1371

John C Campbell Folk School

One Folk School Rd. Brasstown, NC 28902

1-800-365-5724 www.folkschool.com

Coal

Coal is now available through Alex Parubchenko at his shop in Trenton. Please contact Alex or John Chobrda at the shop, Phone # (609) 396-9583.

Open Forges

We want to encourage all to join us at:

Monday Night Open Forge in N.J. Marshall Bienstock is hosting an open forge in his shop at 7 pm almost every Monday night (Please call ahead on holidays to make sure, (732)780-0871)

Monday Night Open Forge

In Orange County

Greg Phillips will be hosting an open forge in his shop in Orange Co. NY. For more information Contact: Greg Phillips, Acorn Forge, 937 Route 17k, Montgomery, NY 12549, (914) 457-5672, Suresign@frontiernet.net

Cheap !!!

I can't locate an engine, so I now have parts to an old Lincoln engine driven welder (2 cylinder, 250 amp) for sale or free to someone who can pick the parts up. Larry Brown— (718)967-4776 Business Members

We would like to thank those who joined with our new Business Membership category
Please show them our support

Ginty's Welding Service, Inc 2 Lee Mack Ave., Danbury, Conn, 06810

Timothy Miller, Artist Blacksmith, Bayport, Long Island, NY (631)419-1185

Marshall Bienstock 663 Casino Dr., Howell, NJ 07731 (732) 938–6577, (732) 780-0871

Lincoln Wolfe 11 Overlook Terrace, Bloomfield, NJ 7003 (973) 338-3913

New York State Designer Blacksmiths Francis Whitaker Ring Project

http://www.abana.org/business/nysdbproject.html

The New York State Designer Blacksmiths is going to engage in a Francis Whitaker ring project, therefore we are looking for volunteers to work on the grille and some to fabricate the rings.

If any questions e-mail me at:

Al Butlak Jr.

1351 Walden Ave

Buffalo, NY 14211-2826

butlak1@mindspring.com

If we are interested in participating in this we should decide soon and maybe get the interested parties together at a forge work out the design and execute it.

Remember soon it will be time to send in your renewals!

If you do not get one contact:


Nate Pettengill,

Membership Chairman

THE SCRAP CORNER

Contributed by **Tim Suter**

I had occasion to cut a good number of 5/16 rivets shorter for a special use. The problem is to hold them secure and cut accurately.



The sketch will help explain what I did.

The holes were drilled and the 3/4 hole chamfered down to about a 1/32 land, note the offset of the 3/4 hole places the land in line with the rivet hole. The two parts were then hardened in super quench. The two mating surfaces polished, lightly greased and bolted together. I snubbed the nut up to barely allow the parts to move and locked it with a jam nut. A stack of washers or suitable spacer under the rivet head controls the length. To keep the gadget small and easy to store for future use I used a temporary thirty six inch handle of crescent wrench and pipe. I put the cutter in my vise, dropped a rivet in the hole arid pulled the handle. It popped that little booger and many others "slicker-n snot on the doorknob". This sheer principal could be adapted to many different uses.



Beginning at 10:00 am, Leigh Morrell will be speaking and demonstrating on his techniques for forging with an eye towards production and efficiency. Use of the power hammer, dies and jigs and other fixtures will be covered.

There will be plenty of time for networking and socializing with your fellow metalworkers. All are welcome, the event is open to the public.

- Safety glasses are required.
- The tradition of tailgating will continue. If you have stuff to sell, please park behind the shop. There is even a forklift to load/unload with so don't be shy! There is plenty of room outside and a limited amount of indoor space available.. (call ahead for indoor space) 845-457-5671

Directions:

This location is the same as last years, The shop of Greg Phillips A.K.A. "A Sure Sign" in Montgomery, NY.

Take NYS Thruway to Newburg, NY Then take Route 17K west about 7 miles to "A Sure Sign" on the left. Any Questions? Call 845-457-5671

New Jersey Blacksmiths Newsletter

"Ron's Snakes"; This is from the ABANA sponsored news group "The Forge"

From: "Ron Reil" <rreil@micron.net>

To: <theforge@qth.net>

Subject: Re: [TheForge] The Friendly Snake...a Step by Step

Here is a short rundown on making the snake as you asked.

First lay the head of the spike back to put the top of the head in line with the shaft of the spike. This is where you may want to pay attention to the short lip of the head so that is will not cause you a cold shut when you flatten the head down to join the shaft. Grind it off or hammer it gently down into the head before you align the head with the shaft.

Draw out the spike to 18" or so, about 3/8" in diameter, paying attention to how a snake is usually built.....that is he has a fatter mid section and is thinner toward the head, with a small neck, at least for the rattlers and such snakes. Certainly not all snakes are built this way, but that is part of the "look" that you want to develop. I need to do better on this part on my next one.

When you round the body remember that they are not really round but have a "flat" belly that you will put the little lines on to imitate the big belly scales.

Looking at the tutorial for the rasp snake by Bill Epps on Anvilfire, he has a great way of adding the rattles if you want a rattle snake, "buzz-tail". I will do that on my next one.

I used my power hammer to rough out the head shape, and found that the drawing dies, the only ones I presently have, do a superb job of putting in the right curves. I had a really good head until I punched the eyes, and then I had problems. I put then too high on the head and used the wrong shape eye.

Do not do any of the detailing of the head until the very end...important, or the scaling during subsequent heats will ruin your detail.

Get the head refined and split the mouth. Be careful here because this is another place I went wrong. I ended up with a mouth to low set on the head. The viper's mouth is more centered. It made my snake look like a friendly horse for a while. Also, split it quite a ways back into the head. A vipers mouth will open the entire head when it strikes.

Leave the mouth open about 30 degrees for now. Find a big finishing nail and cut off the front 3/4 of it and discard, leaving a piece about 3/4" long with the round head of the nail on one end. Flatten the other end, split and shape into the

tongue. If it gets too long trim the tongue to keep it no longer than 3/4" or less.

Hammer refine the entire snake, and in the process do the chisel cuts across the belly for the scales. Once you have the scales cut take a file and remove all the sharp little ridges that the chisel has pushed up to make the snake body smooth to the touch.

At this point you should have your snake about all shaped and ready for the final steps. If there is anything that you don't like about its body conformation fix it now with the hammer or files. The snake should still be in a fairly straight form. Again, you want to be sure the entire body and head are very smooth, hammer refined, as this will determine the end finish of your work.

Choose a drill that is just big enough to allow the ball end of the tongue you forged to drop into the hole it drills, and drill a hole in the back of the open mouth deep enough to reach back all the way through the head to the base of the neck, and to position the tongue as you want it when you place the butt of the tongue in the hole. The reason you want the hole to go so far back is because its how you are going to lock it in place. Its important to keep testing the tongue in the hole as you drill it or you may over-drill, making things difficult later, or making it necessary to forge another longer tongue.

You will now take the last forge heat on the head of the snake, and the snake in general. You may need two heats if you are a little slow with your eye punch. Heat the head to a good red heat, put it in the vise quickly and punch the eyes, and while still hot drop the tongue into the hole and position it the way you will want it in the finished snake (Your only chance is now) and while still hot, place the top of the snakes head on the anvil and using a small ball peen with a relatively "sharp" ball end, hammer the underside of the head to close the hole around the tongue anchor ball. If you use the right shaped ball peen you will end up with a beautiful depression that looks very correct anatomically. This will also close up the mouth to some degree, depending on the angle you hold the head on the anvil. Don't overdue it or you will deform the head to much. The sharp ball end on the hammer will tend to concentrate the blow in such a small area that the head is not deformed too much, and in fact may improve the head by thinning it a little.

Once its cool, dress up the head with files, including a little depression between the eyes and down the forehead. Basically get the head into its final form and use very fine files at the end to eliminate file marks.

To preserve the nice smooth hammer finish on the body of the snake I elected to use my torch to do the final bending and forming of the body. I held the torch in one hand and the tongs in the other with the snake in the vise.

New Jersey Blacksmiths Newsletter

This way each bend was only heated once and I moved on to the next bend in a continuous motion. Using the forge, everything would be heated a number of times and greater scaling would roughen the surface. BTW, the heating you are doing now will help to eliminate any remaining fine file marks due to the light scaling that it will cause.

Once the final shape has been created, and you are happy with it as a finished snake, lightly clean the loose scale off and drop the whole snake into a plastic container of vinegar. A couple of hours should have all the scale cleaned off, including inside the mouth...use a toothbrush in the mouth. Wash very well to remove all vinegar. The results are a sick gray look, but with a fine wire wheel it almost instantly polishes up into a very attractive bright iron finish. At this point I took the torch and took a light heat (purple) on the head and carefully took the head to my brass wire wheel to give the brass highlights I wanted. I then put it on the anvil and using the torch, differentially heated it to obtain various temper colors along the body length....blue-gray in the middle, lightening to a more straw at the tail.

While still hot I then rubbed it down with beeswax, filling the mouth too with liquid wax so that the hole for the tongue was completely filled around the tongue (prevents later corrosion), and then shook out the excess, allowed it to cool and buffed with a clean cloth. It ended up very smooth and has a nice glossy highly colored finish. I should add that you do want to be careful when applying the beeswax. I hold the snake in a cloth while doing so and use the cloth to rub the wax in well, and while I was doing so I accidentally pulled the cloth out from between the snake and my hand. The snake was still very hot and the result was the snake ended up on the other side of the yard and my hand in the slack tub....grin.

All that is left is to test the snake. Place it under the covers of your wife's side of the bed and the results will tell you how effective your work was. If its a really good snake you will be sleeping on the couch for a week. :-)

Ron





The Heart Hook

(by Stephan 0. "Rambo" Clary as shown the Editor and drawn by Tom Grimes)

Using 1/2"X !/4" X 6 ¼" stock. hot cut down center of stock (#1) 2 ¼ inches, punch or drill a nail hole 1/2" below cut. Draw out the three ends, bend over anvil horn and use round nose pliers if needed. Enjoy! (Dr. Heart Hook strikes again!)

From the Tuyere 11/12/99





www.artist-blacksmith.org It may be the only address you need

Building Blocks A "Back to Basics" project

A "Back to Basics" project The Anvils Ring/ Fall 1987 by Dorothy Stiegler Part 4

Part 1

Well, it's fun to be back with you again! This time we're going to start a two-part project that will be a really nice item for your home. When you're finished, don't show it to your mother before you get it nailed down. Mothers like these kinds of things as a rule and you'll make the less it.

rule, and you'll probably lose it!

Start by assembling three 1/2" square pieces cut to the following lengths: 14", 16" and 24". Then get six pieces of 5/16" square, each about 5" long. You will need a hot cutter of some type; an old chisel will work if you don't have a regulation cutter. Round up someone to help you if you don't have a hold-down tool, or if you want it to go faster. If you don't have anyone available, you can do all of this alone. You'll just need to be more patient with yourself.

The three 1/2" square pieces will be similar when finished, and we will do them all at once. You may start with any one of the three; place one end in the fire and take a nice yellow-orange heat. Place the piece over the anvil and—if you are right handed—lift up with your left hand so the steel sits at about a 30 deg. angle from the flat of the anvil. By hammering with the flat face of the hammer also at a 30 deg. angle,

you will point the work.

Turn it one quarter turn every five to six blows. If you hammer the same number of times on each side, you will produce an even short point on the end. Make the point about 1" long. If you keep the work hand up a bit, the taper will remain in the center. After you have reheated, hold the work on it's edge (on the diamond) and overlapping the taper, hammer straight down with flat overlapping blows

Think it through here. If you hold it on its edge and flatten straight down on the top edge, the anvil will flatten the bottom edge at the same time. Leave the other two opposing sides alone, as you will like it

better if these edges remain sharp. I find if I overlap my heats carefully, and deliver flat overlapping blows with my hammer, this draws out very nicely. Make the new flat section about 1/4"1 thick, then wire brush and reheat.

Be careful to turn the piece over fairly often and work back to front, then reverse, then back to front again. This helps avoid any curl and also keeps that flat area even. If the work starts to skew to one side, heat it and whack it with a wooden hammer over a wood block. If you don't have a wooden hammer, you can use a wooden board over wood. This will

keep the edges crisp.

Work your way down the bar, overlapping each heat and hammering flat. If you have trouble getting your hammer to land flat, the handle may be too long. If you have to hold it way up near the head, cut the handle off in 1" segments until it will land flat and you can hold it further back. The end should probably not extend further than 1 1/2" past the height of your hand on a full swing.

If the handle is the correct length and you are hammering flat, the face of the hammer should make contact evenly. If you are still experiencing trouble, check the height of your anvil. If the far corner of the hammer face hits first, then the anvil is too low. If the near corner of the face hits first, the anvil is probably

too high.

When you get to the center—or just past it—turn the piece around in the fire and start over with step one on the other end. Do all three of the 1/2" square pieces like this. I guarantee you will make nice flat overlapping hammer blows by the time you are finished. While you are working, keep the piece flat and true (don't let it creep to one side). If it becomes skewed, get after it right away with the wooden hammer. Be sure to wire brush.

Next, using the hot chisel, run a line down the center of that flat part on front and back. For those not familiar with walking a line, I use a chisel that is rounded on the corners and sharp on all three sides. To help you visually find the center of your stock, lay the hot chisel on its side so the edge appears to be at the center of the stock where you wish to cut. Then stand the chisel up straight and strike. It will cut a nice straight line if you use the following method: To

properly position the chisel as you move down the imaginary centered line, rock it forward from its back corner until it is in an upright position, strike, rock in the same manner again, strike, etc. Try not to lift your hand. If you can keep from tilting the chisel from side to side, you will be able to make a nice straight cut down the center. Keep your eye on the line you want to move along.

out your line while the stock is cold (using the technique described above). Then you can simply run down the line again as you overlap your heats. Cut the final line about 1/8" deep, making sure to cool your hot cutter in the water bucket every three or four blows. This also keeps the temper in your tool. Be sure to wipe it off (on your pants is handy) to prevent the water from cooling your work.

Cut a line down both flat sides on all three pieces. I find that if I begin cutting down one side, reheat the same segment, then flip it over and cut the corresponding area on the other side, it goes faster than if I go all the way down one side and then start over on the other side.

When you've finished the lines, it's time to do the Part 5 twists. I use a fork wrench with another handle welded to the front for leverage. That enables me to use two hands on a twist, which helps keep the twist even. First get a can of water, pinch the front into a spout and put a bucket under the vise about where the twisting will occur. Start the twist by taking a 5" heat about 2 1/2" back from the tip of one end. Put the 2 1/2" into the vice and the wrench out 2 1/2" from the other end. If you're careful never to put a tool on the work anywhere it is going to twist, you'll avoid funnylooking marks where you don't want them, Of course, it will only twist where it's hot anyway.

Now, twist to the right one and a quarter turns, wire brush, and reheat the next 5" or so, overlapping the area of the last quarter turn at the minimum. Next use the spouted can to quench only the area where you put in the full turn, so it won't unwind. Allow the quarter turn area to move freely as you wind to the left this time (wrench way out on the end again). The quarter turn area will unwind and leave a beautifully executed reverse twist, with a nice flat area (short flat).

Wire brush, straighten with the wooden mallet or

piece of wood and place the piece back into the fire again. Reheat, overlapping the last quarter turn area, quench the full turn (don't forget to keep moving the bucket forward to keep water off the shop floor) and twist the opposite way.

Continue this process all the way down the piece of stock (except the last 2 1/2"). If you overlap your heats in this fashion, work slowly using the guench It really helps if you first use a cold chisel to mark can, and try to come out at the same heat each time, you will produce a beautiful back-and-forth twist design evenly spaced down the bar. The veined lines down the flat sides look great twisted and the sharp edges on the opposite sides completely change the shape of the steel from square to a flat diamond.

Well, this is a good place to pause. We'll continue next issue. See you then!

<u>Building Blocks</u>

A "Back to Basics" project The Anvils Ring/Winter 1987/1988 by Dorothy Stiegler

(Second of 2 parts)

Hello again; I hope you had fun with Part I of this project. We will be working with the six pieces you made last time; each should be about 5" long and 5/1 6′ square.

Grip one end of one piece with a tong and heat the other end to an orange-yellow. Go to the anvil and, holding the work flat, hammer straight down making a nice even taper approximately 2" long and twice the width you started with (see Fig. 1). Thin the end nicely and make a smooth transition overall from square to flat. Put the piece in the vise gripping near the square part of the stock— and rasp it evenly around so it looks nice.



Fig. 1