

**Sea-Bird Electronics, Inc.**

13431 NE 20th Street
Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866
service@seabird.com
www.seabird.com

SERVICE REPORT**RMA #: 00001683****Date:** 17-APR-2026**CUSTOMER INFORMATION**

Name: NOAA - PMEL PACIFIC MARINE ENVIRO LAB
Account : 40279844
David Strausz
david.strausz@noaa.gov
206-526-4510

PO Number: 1305M225D0032/1333MJ26F0004
Notes:

Bill To Address

NOAA - PMEL PACIFIC MARINE ENVIRO LAB
7600 SAND POINT WAY NE
SEATTLE, WA, 98115-6349
US

Ship To Address

NOAA - PMEL PACIFIC MARINE ENVIRO LAB
7600 SAND POINT WAY NE
SEATTLE, WA, 98115-6349
US

PRODUCTS SERVICED

Sales Order	Serial	Instrument	Description	Problems Found	Work Performed
	16P35165-4607	16P.LEGACY	(LEGACY) SBE 16Plus (V1/V2) CT(D)	The conductivity cell was found to require cleaning and re-platinization.	Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM22852-1526	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM24246-1678	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM25429-1804	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT		Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
					Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration. Cleaned and

	37SM25541-1865	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	replatinized the conductivity cell. Performed a "Final" Calibration. Performed complete system check and full diagnostic evaluation. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM25541-1869	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Performed a "Final" Calibration. Installed NEW Wet-pluggable style connector(s).
	37SM26834-2026	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM28082-2322	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT		Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM28082-2327	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	No problem found.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM28082-2331	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM29412-1842	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT		Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Installed NEW Wet-pluggable style connector(s).
	37SM36048-3765	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization. My mother board has failed	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Replaced the mother board. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	37SM36048-3770	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity was found to have excessive drift	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the conductivity cell. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
					Perform initial diagnostic evaluation. Performed

	37SM40084-4285	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization. The mother board has failed.	"POST" cruise calibration. Cleaned and replatinized the conductivity cell. Replaced the mother board. Performed a "Final" Calibration. Installed NEW AF24173 Anti-foulant cylinder(s).
	BBFL2W-1418	ECO.LEGACY	(LEGACY) ECO Single Channel	Found Triplet Motor lost internal lubricant.	Replaced Triplet motor. Installed New Triplet Faceplate. Standard Calibration Completed. Eco returned to Customer Settings.
	BBFL2WB-1307	ECO-TRIPLE.LEGACY	(LEGACY) ECO Triple Channel	It was found that the unit required calibration. Channel #3 yielded low dark counts.	Added new 9v batteries, faceplate and shutter. The unit was timed for darks adjustment, calibrated, and standard service was performed. Unit returned with customer settings.
	BBFL2WB-1755	FAA-015297	oo - ECO-Triplet-BBFL2-WB (700,CHL,CDOM)(200,75,375)	It was found that the unit required calibration. Motor internal lubricants had low volume.	Added new 9v batteries, faceplate and wiper. Replaced motor. The unit was calibrated, and standard service was performed. Unit returned with customer settings.
	BBFL2WB-7201	FAA-015257	oo - ECO-Triplet-BBFL2-WB (700,CHL,CDOM)(25,50,375)	Evaluated instrument (BBFL2WB-7201). It was found that channels #1 and #2 had high dark read outs. The motor internal lubricants had low volume. Triage: High darks on Channel 1 and 2. Std srv. [4-1 LP]	Added new 9v batteries, faceplate and wiper. Replaced motor. The unit was timed for dark counts adjustment, tuned, calibrated, and standard service was performed. Unit returned with customer settings. [4-6 LP]
	FLS-028	ECO.LEGACY	(LEGACY) ECO Single Channel	The bulkhead connector was heavily pitted. Triage: G1 board. No problems were found at this time. Std srv.	Added new shutter. Replaced bulkhead connector. The unit was timed, calibrated, and standard service was performed. Unit returned with customer settings.
	FLS-917	ECO.LEGACY	(LEGACY) ECO Single Channel		Added new shutter. The unit was tuned, calibrated, and standard service was performed. Unit returned with customer settings.
	FLSB-2694	FAA-010020	oo - ECO-FL-SB (CHL)(125ug/l)		Added new 9v batteries, faceplate and shutter. The unit was calibrated, and standard service was performed. Unit returned with customer settings.

BILLABLE ITEMS

Instrument	Item	Item Description	Qty
16P35165-4607:16P.LEGACY	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
16P35165-4607:16P.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
		COMPREHENSIVE SERVICE/CALIBRATION	

37SM22852-1526:37SM.LEGACY	SBS-SVC-37	OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM22852-1526:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM24246-1678:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM24246-1678:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM25429-1804:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM25429-1804:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM25541-1865:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM25541-1865:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM25541-1869:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM25541-1869:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM26834-2026:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM26834-2026:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM28082-2322:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM28082-2322:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM28082-2327:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM28082-2327:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM28082-2331:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM28082-2331:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1

37SM29412-1842:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM29412-1842:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM36048-3765:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM36048-3765:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM36048-3770:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM36048-3770:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
37SM40084-4285:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM40084-4285:37SM.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
709-0013:PRAWLER.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
709-0016:PRAWLER.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
BBFL2W-1418:ECO.LEGACY	SBS-SVC-ECOTRIPLE	COMPREHENSIVE SERVICE FOR TRIPLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
BBFL2WB-1307:ECO-TRIPLE.LEGACY	SBS-SVC-ECOTRIPLE	COMPREHENSIVE SERVICE FOR TRIPLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
BBFL2WB-1755:FAA-015297	SBS-SVC-ECOTRIPLE	COMPREHENSIVE SERVICE FOR TRIPLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
BBFL2WB-7201:FAA-015257	SBS-SVC-ECOTRIPLE	COMPREHENSIVE SERVICE FOR TRIPLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
FLS-028:ECO.LEGACY	SBS-SVC-ECOSINGLE	COMPREHENSIVE SERVICE FOR SINGLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
FLS-917:ECO.LEGACY	SBS-SVC-ECOSINGLE	COMPREHENSIVE SERVICE FOR SINGLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
FLSB-2694:FAA-010020	SBS-SVC-ECOSINGLE	COMPREHENSIVE SERVICE FOR SINGLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1

UNBILLABLE ITEMS

Instrument	Item	Item Description	Qty
16P35165-4607:16P.LEGACY	22009	LITHIUM BATTERY, PANASONIC BR 2/3 A-T2SP	3
		BOX, SBE19, 9-CELL, PUMP/1 SENSOR,	

16P35165-4607:16P.LEGACY	35013HT	HEAT TREAT	1
16P35165-4607:16P.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM22852-1526:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM24246-1678:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM24246-1678:37SM.LEGACY	35041.7HT	BOX, SBE37 IMP/SMP, FOAM, 3-5 PER, HEAT TREAT	1
37SM25429-1804:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM25541-1865:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM25541-1869:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM26834-2026:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM28082-2322:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM28082-2327:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM28082-2327:37SM.LEGACY	35041.7HT	BOX, SBE37 IMP/SMP, FOAM, 3-5 PER, HEAT TREAT	1
37SM28082-2331:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM29412-1842:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM36048-3765:37SM.LEGACY	40974	fro - SBE37 MOTHERBOARD W/STRAIN GAUGE /DWG 40974B	1
37SM36048-3765:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM36048-3770:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
37SM36048-3770:37SM.LEGACY	801139	MODULAR MICROCAT COND. CELL TRAY ASSEMBLY	1
37SM40084-4285:37SM.LEGACY	40974	fro - SBE37 MOTHERBOARD W/STRAIN GAUGE /DWG 40974B	1
37SM40084-4285:37SM.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
BBFL2W-1418:ECO.LEGACY	MAA-230330	FACEPLATE, Triplet-S, ECO	1
BBFL2W-1418:ECO.LEGACY	BAA-537894	ASSY, motor, wiper, Triplet-W	1
BBFL2WB-1307:ECO-TRIPLE.LEGACY	MAA-230330	FACEPLATE, Triplet-S, ECO	1
BBFL2WB-1307:ECO-TRIPLE.LEGACY	BAA-251621	ASSY, WIPER, TRIP-W or ECO-V2	1
BBFL2WB-1755:FAA-015297	MAA-230330	FACEPLATE, Triplet-S, ECO	1
BBFL2WB-1755:FAA-015297	BAA-537894	ASSY, motor, wiper, Triplet-W	1
BBFL2WB-1755:FAA-015297	BAA-251621	ASSY, WIPER, TRIP-W or ECO-V2	1
BBFL2WB-7201:FAA-015257	MAA-230330	FACEPLATE, Triplet-S, ECO	1
BBFL2WB-7201:FAA-015257	BAA-251621	ASSY, WIPER, TRIP-W or ECO-V2	1
FLS-028:ECO.LEGACY	ELE-BLK-00014	Micro Connector Bulkhead 6 Pin	1
FLS-028:ECO.LEGACY	BAA-000017	ASSY, Shutter, CCW, Curved, ECO	1
FLS-917:ECO.LEGACY	BAA-000017	ASSY, Shutter, CCW, Curved, ECO	1
FLSB-2694:FAA-010020	MAA-220524	ECO faceplate copper shuttered	1

FLSB-2694:FAA-010020	BAA-000017	ASSY, Shutter, CCW, Curved, ECO	1
FLSB-2694:FAA-010020	EXA-ZX0064	BATTERY, 9v, Lithium	6