



Sea-Bird Electronics, Inc.
13431 NE 20th Street
Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866
service@seabird.com
www.seabird.com

SERVICE REPORT

RMA #: 00002009

Date: 12-JUN-2026

CUSTOMER INFORMATION

Name: NOAA - PMEL PACIFIC MARINE ENVIRO LAB
Account : 40279844
David Strausz
david.strausz@noaa.gov
206-526-4510

PO Number: 1305M225D0032
Notes:

Bill To Address

NOAA - PMEL PACIFIC MARINE ENVIRO LAB
7600 SAND POINT WAY NE
SEATTLE, WA, 98115-6349
US

Ship To Address

NOAA - PMEL PACIFIC MARINE ENVIRO LAB
7600 SAND POINT WAY NE
SEATTLE, WA, 98115-6349
US

PRODUCTS SERVICED

Sales Order	Serial	Instrument	Description	Problems Found	Work Performed
	16-50217	16P.1010	00 - SBE16PLUS, NO PRESSURE, PLASTIC, XSG, RS-232	No problems found.	Performed initial diagnostic evaluation. Performed "POST" cruise calibration. Performed complete system check and full diagnostic evaluation. Installed (2) NEW AF24173 Anti-foulant cylinders.
	16-50236	16P.1010	00 - SBE16PLUS, NO PRESSURE, PLASTIC, XSG, RS-232	No problems found.	Performed initial diagnostic evaluation. Performed "POST" cruise calibration. Performed complete system check and full diagnostic evaluation. Installed (2) NEW AF24173 Anti-foulant cylinders.
	16P31373-4425	16P.LEGACY	(LEGACY) SBE 16Plus (V1/V2) CT(D)	No problems found.	Performed initial diagnostic evaluation. Performed "POST" cruise calibration. Performed complete system check and full diagnostic evaluation. Installed (2) NEW AF24173 Anti-foulant cylinders. Verified log amp still functions at voltage channel 3 (V3). Firmware upgrade not available for specific model of sensor.
	16P31373-4426	16P.LEGACY	(LEGACY) SBE 16Plus (V1/V2) CT(D)	No problems found.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Performed complete system check and full diagnostic evaluation. Installed (2) NEW AF24173 Anti-foulant cylinders. Verified log amp still functions at voltage channel 3 (V3). Firmware upgrade not available for specific model of sensor.
	FLSB-2693	FAA-010020	00 - ECO-FL-SB (CHL)(125ug/l)	Found Eco requires Standard Calibration No problems were found at this time. Std srv.	Installed 6 new 9V Batteries, Faceplate and Shutter. Standard Calibration Completed. Eco returned to Customer Settings.
	FLSB-3073	FAA-010020	00 - ECO-FL-SB (CHL)(125ug/l)	Found Eco requires Standard Calibration No problems were found at this time. Std srv.	Installed 6 new 9V Batteries, Faceplate and Shutter. Standard Calibration Completed. Eco returned to Customer Settings.
				Found Eco Responds to 1 command then must be shut	

	FLSB-603	ECO.LEGACY	(LEGACY) ECO Single Channel	down, no power applied, for 30 seconds. Then apply power, give new command. Eco will not take commands from Test Bed. No Firmware updates available. Bulkhead conn is heavily pitted. Replace battery flange. Replace, ECO label as well. High darks readings at 87 avg.	G-2 unit. ECO repair would require a processor that is no longer available (discontinued). Sensor to be returned as-is.
--	----------	------------	-----------------------------	--	---

BILLABLE ITEMS

Instrument	Item	Item Description	Qty
16-50217:16P.1010	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
16-50217:16P.1010	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
16-50236:16P.1010	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
16-50236:16P.1010	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
16P31373-4425:16P.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
16P31373-4425:16P.LEGACY	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
16P31373-4426:16P.LEGACY	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
16P31373-4426:16P.LEGACY	REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE PN 801542.1 (FRRF)	2
FLSB-2693:FAA-010020	SBS-SVC-ECOSINGLE	COMPREHENSIVE SERVICE FOR SINGLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1
FLSB-3073:FAA-010020	SBS-SVC-ECOSINGLE	COMPREHENSIVE SERVICE FOR SINGLE CHANNEL ECOS. DOES NOT INCLUDE OPTICS HEAD REPLACEMENT (FRRF)	1

UNBILLABLE ITEMS

Instrument	Item	Item Description	Qty
16-50217:16P.1010	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
16-50217:16P.1010	35013HT	BOX, SBE19, 9-CELL, PUMP/1 SENSOR, HEAT TREAT	1
16-50236:16P.1010	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
16-50236:16P.1010	35013HT	BOX, SBE19, 9-CELL, PUMP/1 SENSOR, HEAT TREAT	1
16P31373-4425:16P.LEGACY	35013HT	BOX, SBE19, 9-CELL, PUMP/1 SENSOR, HEAT TREAT	1
16P31373-4425:16P.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
16P31373-4426:16P.LEGACY	35013HT	BOX, SBE19, 9-CELL, PUMP/1 SENSOR, HEAT TREAT	1

16P31373-4426:16P.LEGACY	801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
FLSB-2693:FAA-010020	EXA-ZX0064	BATTERY, 9v, Lithium	6
FLSB-2693:FAA-010020	BAA-000017	ASSY, Shutter, CCW, Curved, ECO	1
FLSB-2693:FAA-010020	MAA-220524	ECO faceplate copper shuttered	1
FLSB-3073:FAA-010020	BAA-000017	ASSY, Shutter, CCW, Curved, ECO	1
FLSB-3073:FAA-010020	MAA-220524	ECO faceplate copper shuttered	1
FLSB-3073:FAA-010020	EXA-ZX0064	BATTERY, 9v, Lithium	6
FLSB-603:ECO.LEGACY	MAA-220524	ECO faceplate copper shuttered	1
FLSB-603:ECO.LEGACY	BAA-000034	ASSY, Battery Flange, ECO	1
FLSB-603:ECO.LEGACY	SBS-SVC-OTHER	SPECIFIC SERVICE REQUEST - CHECK DETAILED NOTES (FRRF)	1
FLSB-603:ECO.LEGACY	BAA-000017	ASSY, Shutter, CCW, Curved, ECO	1
FLSB-603:ECO.LEGACY	EXA-ZX0064	BATTERY, 9v, Lithium	6