Contoso Safety 360

⊠Hazardous	☐At Risk	□Safety	□Safety	
Condition	Behavior	Suggestion	Recognition	
⊠Equipment		\square Material Han	☐ Material Handling	
☐Slips, Trips, Falls		☐Spill, Release	☐ Spill, Release, Environmental	
□Electrical		\square PPE	□PPE	
□Ergonomics		Other Safety	⊠Other Safety	
⊠Significant		□ Not Significa	☐ Not Significant	
Findings: Mold plate was thrown out of CNC. Magnetic Plate was being used				
Mold went through	Plexi Glass Roof.			_
Suggested Solutions:				
Submitter:				
-	Tower Room	Date: July 26,	2021	
	TOWEI NOOIII	Date. July 20,	2021	
Owner: Etleva Hysa				
Solutions:				
Target Date:		Close Date:	Close Date:	
Submitter Approval:				