



Avant Service Bulletin 28. 03. 2011

The boomerang part of the Avant boom P/N: **A47000**.



If such a boomerang gets damaged, or it has worn out, there is a now stronger new version available, and this will automatically be sent to replace the original part including a new part number.

The new assembly part number is : **A411430**.

This assembly includes following items:

2 pcs	p/n A411429	new thinner S=6 spacer rings
2 pcs	p/n A411432	new longer pins
2 pcs	p/n 72798	grease nipple
2 pcs	p/n 64912	bushing bearing
1 pcs	p/n A411418	boomerang

This renewed boomerang assembly is interchangeable with the old one.



New spare part
No: **A411430**