

## Railcore II wiring diagram



- A -Connect X-Stop here
- B -Connect Y-Stop here
- C-Connect Bed Heater
- Connect Extruder motor here
- Connect Rear (X) motor here
- F-Connect Front (Y) motor here
- G -Connect Hotend FAN
- H-Connect HotEnd Blower FAN here
- Connect Heater Bed
- Connect Bltouch two wire leads here (note polarity) Use left most pins
- Connect Duex5 ribbon cable here.. Tuck under/in between boards.
- Connect hotend
  Thermister here



- K-Connect Duex5 ribbon cable here.. Tuck under/in between boards.
- M Three wire cable from Bltouch (brown on right side)
  - Z-Stepper motor (right side motor)
  - Z-Stepper motor (Rear left motor)
  - Z\_Stepper motor (Front left motor)