Military Institute of Science & Technology

Dept. of computer Science & Engineering

Computer Interfacing

CSE - 405

Term Paper

Md. Nawal Rahman, CSE-22(A)

10-202214049

Topics

i) Daisy chain Interrupt handling

ii) DMA controller Codes

iii) i) Stepper Motors

ii) Assembly code for stepper motors

1) Daisy chain Interrupt handling



5 Interrupts INT1 > INT2 > INT3 > INT4 > INT5 in a daisy chain priority scheme. If INT3 in running & INT1 becomes active, 2 possible cases

Daisy chain Interrupt

Nested Interrupt Enabled

- IACK for INT1
- Suspend ISR for INT3
- Save INT3 credentials in stack
- Provide service for INT1
- Pop INT3 after service providing & provide INT3.

Nested Interrupt disabled

- Complete INT3 service.
- Then complete INT4, INT5
- After a complete cycle, then resume to INT1.



11) Audio sample stored in memory 4000H - 47FFH

Sound card's playback buffer 5000H - 57FFH

Ch2 src, Ch3 destination

Automate transfer of audio sample using DMA.

Need to write control register words for DMA controller

Transfer size 2KB, byte-by-byte transfer

```
DMA_BASE EQU 00H ; Base I/O port for DMA

START:
    MOV AL,0FFH
    OUT 0AH, AL ; disable all channels
    OUT 0DH, AL ; Reset controller
    OUT 0CH, AL ; clear flip flop
; Ch2 src 4000H-47FFH.
    MOV AL, 00H
    OUT 04H, AL ; Lower byte 4000H
    MOV AL, 40H
    OUT 04H, AL ; high byte 4000 H

    MOV AL, 00H
    OUT 05H, AL ; Lower byte of (2048-1 = 07FFH)
    MOV AL, 08H
    OUT 05H, AL ; high byte
```

```
; Ch3 setup    5000H - 57FFH

MOV AL, 00H
OUT 06H, AL    ; 5000 → 5000
MOV AL, 50H
OUT 06H, AL    ; 5000 → 5000

MOV AL, 00H
OUT 07H, AL    ; 07FF → [0800 - 1] → 0800
MOV AL, 08H
OUT 07H, AL    ; 0800

; Set mode registers
; Ch2 ; memory read 01, single transfer 01
; ch 3 ; memory write 10, single transfer 01

MOV AL, 4AH    ; ch 2 single trnx, rd
OUT 0BH, AL
MOV AL, 53H    ; ch 3 single trnx, write
OUT 0BH, AL

; UNMASK channels
MOV AL, 0FBH   ; ch 2 enable
OUT 0AH, AL
MOV AL, 0FFH   ; ch 3 enable
OUT 0AH, AL

HLT

END START
```

3) i)

npn darlington pair is used for current amplification

half step:

i) Allows 8 step per sequence

ii) In full step, stepper motor armature has a positioning of 45°, 135°, 225°, 315°, In full step, the armature gets an addition of 4 angles 0°, 90°, 180°, 270°

∴ total of 8 angles 0°, 45°, 90°, 135°, 180°, 225°, 270°, 315°, and returning to 360° ≃ 0°

iii) The 8 step rotation can be shown below:





for half step the input sequences on switches shall be

step	SW1	SW2	SW3	SW4
1	1	0	0	0
2	1	1	0	0
3	0	1	0	0
4	0	1	1	0
5	0	0	1	0
6	0	0	1	1
7	0	0	0	1
8	1	0	0	1

0 = OFF
1 = ON



and the repeat goes on

Above shown is the procedure of half-step operation with stepper motor. I have drawn the system based on clock-wise rotation, with drawing & interfacing connected with µp 8086 & 8255 PPI.

3) ii) An assembly language to rotate stepper motor one full rotation half step mode :

```
PORT EQU 40H ; Stepper motor ctrl port
STEPSEQ  09H, 08H, 0CH, 04H, 06H, 02H, 03H, 01H

AGAIN: MOV SI, OFFSET STEPSEQ ; Pointer for STEPSEQ table
       MOV DX, PORT

STEP_LOOP:
       MOV AL, [SI] ; Get step pattern
       OUT DX, AL   ; Otp to motor
       CALL DELAY
       INC SI       ; Move to next step
       CMP SI, OFFSET STEPSEQ +8 ; End of sequence ?
       JB STEP_LOOP ; If no, repeat
       LOOP AGAIN : Repeat full rotation
       RET
ROTATE ENDP

DELAY  PROC NEAR
       MOV BX, 0FFFFH
WAIT : DEC BX
       JNZ WAIT
       RET
DELAY  ENDP
```

```
ROTATE PROC NEAR
       MOV CX, 64
```

for 8 steps in a half step motor, sequence shall be.

Step	SW3	SW2	SW1	SW0	Hex
1	1	0	0	1	09 H
2	1	0	0	0	08 H
3	1	1	0	0	0C H
4	0	1	0	0	04 H
5	0	1	1	0	06 H
6	0	0	1	0	02 H
7	0	0	1	1	03 H
8	0	0	0	1	01 H



sequence is in anti-clockwise rotation