## #include<p18f4550.inc>

```
n equ D'3'
lp_cnt set 0x10

org 0x00
goto start
org 0x08
retfie
org 0x18
retfie

start movlw n
movwf lp_cnt,A

loop rlncf 0x15,F,A

sum_lp decfsz lp_cnt,F,A
goto loop
nop
```

end