



BV No. 236620

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	Periodic visual/inst + functional test Carried out on SELF PROPELLED EWP as per ARAMCO GI 7.0.30, ANSI A92.6 and Equipment found Satisfactory at the time of Inspection.	

RECEIVER NAME:

THAISEER

SIGNATURE:

... INSPECTOR NAME:

TEETH / 800/919

BADGE#:

TELEPHONE NO.:

Q55 222 803

... TELEPHONE NO.:

0556486924