



Previous Sticker
No. 21-6046 Issued By BV

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]

RECEIVER NAME: THAISER SIGNATURE: [Signature] INSPECTOR NAME: M. O'Malley
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 1-800-0000