



Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

i Ross

RECEIVER NAME: ARJF SIGNATURE: [Signature] INSPECTOR NAME: Morton
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80019106