
Temperature and **Humidity Detector** Exit OFF ON shut off [!= battery] when [power_out] / switch to battery power [= battery] mode after(10m) **PAUSE**



ACTIVE Do: GREEN_LED on OnExit: GREEN_LED off **CONFIGURING** [in_operation] [else] set / in_operation := true Invalid Parameter(s) MONITORING Skip Configuration when [inactivity > 2m] reset / beep **ERROR**

