Members in Attendance

- Josh Mendez (Sponsor/Advisor)
- Nathan Truong
- Felix Moss
- Annika Boyd
- Eisa Alsharifi

Agenda

- PCB Work

Notes

- Full PCB looks good for Josh
- MAX1032 PCB may need work
- Some components need to be soldered on both sides of the PCB
 - The components that need this are the chips that lay flat on the board
 - Can be fixed by slightly lifting the parts up and then soldering them to the board
 - Add VIAs next to microcontroller pins
- We used the wrong ADC footprint
 - Need to reroute the board
 - Board was rerouted during the meeting
- Going to print the PCB after the meeting
- Go to get the parts needed
- Desoldered a MAX1032 from one of Josh's previous projects for use in our own
 - JOSH TOUCHED THE SOLDERING IRON WITH HIS FINGER????