

Incident Report INC_007 — Hydraulic System Failure

Downtime Incident Report · Severity: Major

Doc ID	INC-007
Date of Incident	2026-07-10
Plant / Location	Plant A (Pune)
Line / Machine	Assembly Line — Assembly_Line_5
Shift	Night
Operator on Duty	OP-096
Downtime Code	DT-01 — Hydraulic System Failure

1. Summary

On 2026-07-10, machine Assembly_Line_5 (Assembly Line) at Plant A, Pune experienced an unplanned stoppage of 231 minutes during the Night shift, logged under downtime code DT-01 (Hydraulic System Failure). This is classified Major severity per the Error_Code_Handbook and exceeds the 120-minute incident-filing threshold defined in Plant_Maintenance_Policy section 5.

2. Description of Failure

The shared hydraulic power unit supplying the station's lift/tilt fixture lost pressure, triggering a DT-01 fault and stopping the line to prevent a dropped-fixture hazard.

3. Root Cause

A fitting on the power unit's return line loosened under vibration, allowing a slow fluid leak that went undetected between shift checks.

4. Corrective Action Taken

Retorqued and thread-locked the fitting, topped up hydraulic oil, and added the fixture to the daily pre-shift visual check per Inspection_Checklist.

5. Downtime Impact

Metric	Value
Total downtime	231 minutes
Downtime code	DT-01 — Hydraulic System Failure
Machine	Assembly_Line_5 (Assembly Line)
Shift / Operator	Night / OP-096

6. Preventive Follow-Up

- Work order raised to inspect equivalent hydraulic components on sister machines of the same type.
- Reviewed against Lubrication_Schedule and PM_Guide to confirm hydraulic PM interval was followed.
- Corrective action and parts usage logged in CMMS and cross-referenced to Hydraulic_Maintenance_SOP.