

Incident Report INC_010 — Hydraulic System Failure

Downtime Incident Report · Severity: Major

Doc ID	INC-010
Date of Incident	2026-05-13
Plant / Location	Plant A (Pune)
Line / Machine	CNC Milling — CNC_Milling_6
Shift	Morning
Operator on Duty	OP-084
Downtime Code	DT-01 — Hydraulic System Failure

1. Summary

On 2026-05-13, machine CNC_Milling_6 (CNC Milling) at Plant A, Pune experienced an unplanned stoppage of 228 minutes during the Morning shift, logged under downtime code DT-01 (Hydraulic System Failure). This is classified Major severity per the Error_Code_Handbook and exceeds the 120-minute incident-filing threshold defined in Plant_Maintenance_Policy section 5.

2. Description of Failure

The hydraulic workholding clamp circuit lost pressure mid-cycle, tripping a DT-01 hydraulic fault and halting the spindle to prevent an unclamped-part condition.

3. Root Cause

Internal seal wear in the clamp cylinder allowed internal leak-by, gradually reducing clamp pressure below the safety threshold.

4. Corrective Action Taken

Replaced the cylinder seal kit per Hydraulic_Maintenance_SOP and verified clamp pressure held steady across 5 cycles before restart.

5. Downtime Impact

Metric	Value
Total downtime	228 minutes
Downtime code	DT-01 — Hydraulic System Failure
Machine	CNC_Milling_6 (CNC Milling)
Shift / Operator	Morning / OP-084

6. Preventive Follow-Up

- Work order raised to inspect equivalent hydraulic components on sister machines of the same type.
- Reviewed against Lubrication_Schedule and PM_Guide to confirm hydraulic PM interval was followed.
- Corrective action and parts usage logged in CMMS and cross-referenced to Hydraulic_Maintenance_SOP.