

General Plant Safety Guidelines

Safety · All Personnel

Doc ID	SAF-GEN-001
Version	6.1
Effective Date	2026-01-01
Owner	EHS Department
Scope	All plants, all personnel and contractors

1. General Requirements

- PPE (safety glasses, steel-toe boots) is mandatory on the production floor at all times.
- Hearing protection is required within marked high-noise zones (Press Line bays).
- No loose clothing, jewelry, or unrestrained long hair near rotating or conveyor equipment.

2. Lockout-Tagout (LOTO)

- 1 Notify affected operators before beginning LOTO.
- 2 Shut down the machine using normal stop procedure, then isolate all energy sources (electrical, hydraulic, pneumatic).
- 3 Apply personal lock and tag to each isolation point.
- 4 Verify zero energy state by attempting a normal start (must fail) and, for hydraulic systems, confirming zero pressure on the gauge.
- 5 Only the technician who applied a lock may remove it upon job completion.

3. Hydraulic & Pressurized System Safety

Hydraulic systems (Press Line, CNC clamping circuits) must be fully depressurized before any fitting is loosened. Refer to Hydraulic_Maintenance_SOP for the full depressurization sequence. Fluid injection injuries from pinhole leaks are a medical emergency — seek immediate treatment even if the wound looks minor.

4. Emergency Procedures

- Emergency stop (E-stop) buttons are located at every station — know your nearest one before starting a shift.
- Report all injuries, near-misses, and equipment incidents to the shift supervisor immediately.
- Incidents involving injury must be documented per the incident reporting process referenced in Plant_Maintenance_Policy section 5.

■ In case of fire, hydraulic fluid injection injury, or entrapment: stop work, alert the area, and call the plant emergency line before attempting first aid.