

	Safety Management Manual
Procedure Number:	SMM/c/ac/003
Procedure Title:	Internal Safety Audit and corrective action
Page No.	1 of 4

AUDITOR:	NAME OF VESSEL
----------	----------------

LOCATION OF AUDIT: MALDIVES	DATE OF AUDIT: 3RD FEBUARY 2023
------------------------------------	---

TYPE OF AUDIT:	INTERNAL AUDIT FOLLOW UP PRE ASSESSMENT
----------------	--

NAME AND ADDRESS OF COMPANY

OPENING MEETING 0830	CLOSING MEETING 1615
-----------------------------	-----------------------------

FINDINGS	ISM/ISPS OR SMS REFERENCE
-----------------	--------------------------------------

	Safety Management Manual
Procedure Number:	SMM/c/ac/003
Procedure Title:	Internal Safety Audit and corrective action
Page No.	2 of 4

Non Conformity – Crew Documents, during review it was observed various obsolete and or missing documents where noticed. Correct documents are to be sent to the crew administer - Closed out during Audit	ISM Code 11.2.1
Non Conformity – Entrance to Engine Room shall have relevant Personal Protective Equipment (PPE) signs posted (to all entrances)	ISM Code 1.2.2.2
Observation – Official Log Book. Weekly inspections of crew quarters and conditions to be logged as required	ISM Code 1.2.3.1
Observation – Official Log Book entries should run in consecutive dates, if an entry is entered late note should entered explaining reasoning	ISM Code 1.2.3.1
Observation – BA Team to remove all personal items before donning equipment. Recommended a “throw” basket is provided.	ISM Code 7
Observation – Drill reports, any training needs identified during the de- brief should be discussed during the monthly safety and security meeting and recorded.	ISM Code 1.2.2.3
Observation – General Signs, a number of signs need to be put in place including rescue crane controls location, damage control room and rescue boat crane (man riding crane for rescue boat launching only)	ISM Code 7.0
Observation - SOPs it is noted that the crew has implemented many yacht specific SOP's. These will be required to be posted in relevant areas.	ISM Code 11.2.1
Observation - Standard compass errors to be recorded once per watch as per STCW VIII Part 4 / 34.2	ISM Code 1.2.3.2

	Safety Management Manual
Procedure Number:	SMM/c/ac/003
Procedure Title:	Internal Safety Audit and corrective action
Page No.	3 of 4

Observation Oil Record Book. It was noted an earlier entry for the bunkering of fuel had been made in M ³ . Later entry was in correct format MT. This is to be continued. (a copy of MEPC.1/Circ.736/Rev 2 left onboard for reference)	ISM Code 1.2.3.1
Recommendation – Recommend periodic fuel analysis schedule be developed.	ISM Code 1.2.3.1
Recommendation – Anchor chain marks, an index for relevant length / colour code to be posted in suitable location.	ISM Code 7.0
Recommendation – Planned Maintenance, work should continue in this area with (Deck) programming further target dates e.g. Annual checks. Reference (Eng) should be made to the relevant MSC for FFE equipment. (a copy of MSC.1/Circ.1432 was left onboard for reference)	ISM Code 10.4
Recommendation – Emergency escape, guest area to be accessed for ease of use, any relevant findings to be incorporated into the Guest Safety briefing.	ISM Code 8.1

Audit programme

THE ASSESSMENT BEGAN WITH AN OPENING MEETING. THE DISCUSSION COVERED THE SCOPE AND PURPOSE OF THE AUDIT, THE AUDIT SCHEDULE AND PROCESS AND THE ESCORT'S RESPONSIBILITIES.

IT WAS NOTED THAT THE SMS HAS BEEN IN OPERATION ON BOARD FOR A SHORT WHILE AND IS FULLY IMPLEMENTED AND IN GOOD HEALTH.

DEFECT REPORTING, INCIDENT AND ACCIDENT REPORTING TO THE COMPANY WAS IN USE AND EFFECTIVE.

THE AUDIT ENDED WITH A CLOSING MEETING. THE DISCUSSION INCLUDED A REVIEW OF THE VERIFICATION ACTIVITIES AS CARRIED OUT, PRESENTATION OF FINDINGS AND REVIEW OF THE NOTABLE OBSERVATIONS MADE DURING THE COURSE OF THE INTERNAL AUDIT.

Summary

	Safety Management Manual
Procedure Number:	SMM/c/ac/003
Procedure Title:	Internal Safety Audit and corrective action
Page No.	4 of 4

THE AUDITOR GATHERED OBJECTIVE EVIDENCE OF COMPLIANCE THROUGH THE OBSERVATION OF DAILY ACTIVITIES, INTERVIEWS OF PERSONNEL AND THE EXAMINATION OF RELEVANT RECORDS.

THIS INFORMATION WAS COMPARED TO EXISTING POLICIES AND PROCEDURES AND THE REQUIREMENTS OF THE ISM & ISPS CODES TO DETERMINE THE LEVEL OF COMPLIANCE OBTAINED.

THIS EVIDENCE WAS DOCUMENTED WITHIN THE AUDITOR'S CHECKLISTS, NOTES, EXAMPLES AND THIS REPORT.

The BRIDGE yacht IS RUN IN A VERY PROCEDURALISED ENVIRONMENT WHICH PROVIDES A VERY SAFE AND HEALTHY PLATFORM FOR THE CREW AND PASSENGERS.

THE AUDITOR WOULD LIKE TO THANK THE CREW FOR THEIR HOSPITALITY DURING THE AUDIT.

IN ACCORDANCE WITH THE REQUIREMENTS OF THE ISM & ISPS CODES CERTIFICATION PROGRAM, THE AUDITOR PROVIDED THE FOLLOWING COMMENTS FOR COMPLIANCE WITH THE ISM & ISPS CODES:

TOTAL NUMBER OF NON-CONFORMITY NOTES WRITTEN:	
MAJOR NON-CONFORMITIES:	0
NON-CONFORMITIES:	2
NUMBER OF OBSERVATIONS WRITTEN:	8
NUMBER OF COMMENTS / RECOMMENDATIONS:	4

NON-CONFORMITY NOTES ARE ATTACHED TO THIS REPORT.	One
---	-----

Signed:

Date: 3rd February 2023

Print Name:

Position: DDPA