Inputs

Outputs

| Outputs | | |
|---------|---------|-----------------------|
| Address | PowerUp | Description |
| 0 | | Seal Die Power(S&R) |
| 1 | | Cut Die Power(S&R) |
| 2 | | Servo Reset |
| 3 | | Servo Power |
| 4 | | Seal Die UP |
| 5 | | Seal Die DOWN |
| 6 | | Cut Die UP |
| 7 | | Cut Die DOWN |
| 8 | | Seal Heat Enable(S&R) |
| 9 | | Cut Heat Enable(S&R) |
| 10 | | |
| 11 | | Valve Welding Heater |
| 12 | | clutch brake |
| 13 | | valver signal |
| 14 | | hsc reset |
| 15 | | die heat contactor |
| 16 | | solid state relay |
| 48 | | Die Cylinder |
| 49 | | Die Cylinder |
| 50 | | Bottom Unwind Reverse |
| 51 | | Bottom Unwind Power |
| 52 | | Top Unwind Reverse |
| 53 | | Top Unwind Power |
| 54 | | Batch Counter Reset |
| 55 | | Batch Counter |
| 56 | | Valver Cycle |
| 57 | | Die Heater |
| 58 | | Die Cooling Fan |
| 59 | | servo JOG |
| 60 | | servo DISTANCE |
| 61 | | servo REGISTRATION |

| 62 | Trim Roller |
|----|-----------------------|
| 63 | new air valve 11-3-07 |