PG&E Field Audit Report

Date: October 10, 2025

Location: Stockton Division

Inspector: John Smith

Infractions Found:

- 1. TAG-2 pole replacement required deteriorated pole
- 2. Missing grounding on transformer installation
- 3. Crew used incorrect cable type for overhead lines
- 4. Safety equipment not properly staged at work site
- 5. 07D-1 clearance violation near power lines

Required Actions:

- Replace pole within 30 days (TAG-2)
- Install proper grounding immediately
- Replace cable with approved type
- Retrain crew on safety protocols