2025 PVN FME Q1 Work Report

Dept.: BG6-Manufacturing&Operation Management Center.-Vietnam Manufacturing Div.-PVN1 Factory-FME Dept.-Automation Sec.
Name: Arthur Nguyen 阮春松
Date: 2025/03/19

BG6 PVN

Self-Work Responsibilities

1. Responsible for all laser machines in the Automation Sec. (HAN*s LASER, HG LASER, LASERVALL, HANSUN COOL, QUICK 6102A1, AIR CLEANER SRA).

2. Assist the supervisor in managing the workshop (discipline, 5S, machines, etc.). Ensure stable production of machines so that products can be put into warehouse in advance and shipped out smoothly.

3. Check and handle arising errors as well as daily machine maintenance.

4. Patrol the lines at any time to detect and handle abnormalities in a timely manner.

5. Training OP (instruct workers to control the machine, how to operate the machine safely, what needs attention and should not do when operating the machine).

6. Responsible for managing projects related to laser engraving machines

7. Receive customer plan for new project to setting machine.

8. Receive drawings of new products from customers to adjust machines and change machine parameters to match the drawings sent by customers.

9. Report machine progress to management and improve machine if necessary.

FME BG6 PVN

BG6 PVN

Q1-2025 Work Results

Time	Work Results
2024 Q4	1. Setup laser engraving machine on UI UF-Wifi6 line (F5-5N)
	2. Setup laser engraving machine on UI UDR7 line (F4-5A)
	3. Setup two laser engraving machine on UI U7 Lite line (F5-5A)
2025 Q1	4. Jig of UI UDR7 laser engraving machine causes the product to be misaligned after laser engraving, so it has been improved
	5. Re-adjust the UI U6-Pro laser etching machine to replace the Gucci Pavilion laser etching machine due to broken.

FME BG6 PVN

Detailed Description of Work Results

1. Setup laser engraving machine on UI UF-Wifi6 line (F5-5N).

Transfer machine from PHP company to PVN company → Machine transferred to F1- 3F → Drag the machine to IE Layout location → Install the equipment in the complex Pull the power and air source (PC, network cable, ...) → Turn on the equipment to check if there are any abnormalities → Connect I\O and check if the functional safety door is stuck → Adjust the focus of the laser head so that the laser beam has the strongest power → Complete laser engraving machine installation → Contact ATS to complete program Online → Adjust product according to customer's artwork.





Detailed Description of Work Results

2. Setup laser engraving machine on UI UDR7 line (F4-5A).

Machine transferred to F1- 3F → Drag the machine to IE Layout location → Install the equipment in the complex Pull the power and air source (PC, network cable, ...) → Turn on the equipment to check if there are any abnormalities → Connect I\O and check if the functional safety door is stuck → Adjust the focus of the laser head so that the laser beam has the strongest power → Complete laser engraving machine installation → Contact ATS to complete program Online → Adjust product according to customer's artwork.





Detailed Description of Work Results

3. Setup two laser engraving machine on UI U7 Lite line (F5-5A).

Machine transferred to F1- 3F → Drag the machine to IE Layout location → Install the equipment in the complex Pull the power and air source (PC, network cable, ...) → Turn on the equipment to check if there are any abnormalities → Connect I\O and check if the functional safety door is stuck → Adjust the focus of the laser head so that the laser beam has the strongest power → Complete laser engraving machine installation → Contact ATS to complete program Online → Adjust product according to customer's artwork.






BG6 PVN

Detailed Description of Work Results

4. Jig of UI UDR7 laser engraving machine causes the product to be misaligned after laser engraving, so it has been improved.

Issue description

The material fixing pin is not tight, plus there is still a gap on both sides of the jig, so when the jig is closed, it may still be misaligned during laser engraving, causing the laser engraving NG rate up to 50%.

Cause Analysis

Because the Jig still has a certain gap and the plug is not tight, when OP puts material into the JIG and closes it, it can still be offset to both sides, causing the laser engraving to be NG. Causing the laser engraving NG rate up to 50%.



Improve results



After changing the Jig, the improvement can be seen immediately. The laser engraving deviation rate is significantly reduced, along with the simple operation of the new Jig, it helps OP get used to it easier and faster, improving productivity.



FME BG6 PVN

Detailed Description of Work Results

Before improvement



After improvement



Detailed Description of Work Results

5. Re-adjust the UI U6-Pro laser etching machine to replace the Gucci Pavilion laser etching machine due to broken.

Issue description

The laser head of the LaserVall engraving machine at the Pavilion line did not meet the capacity, causing the product after laser engraving to be pale, so the Pavilion laser engraving machine had to be replace U6-Pro engraving laser.

Cause Analysis

Because the laser head does not have enough power, laser engraving causes the product to have irregular faint colors.

Improve results

After transfer the U6-Pro laser engraver to the Pavilion line, the faint engraving no longer occurs.

Future work and Self-Development Plans

Time	Work and Self-Development Plans
2025 Q1~	1. Improve communication skills.
	2. Improve English, Chinese skills.
	3. Improve problem solving skills (5W-1H).
	4. Improve presentation skills.
	5. Improve responsibility for work more.

Recommendations for Departments

Hope the department provides more computers for the engineers.

The department should have team building trips to connect everyone in the department as well as make the department more united.

There should be small parties so that everyone in the department can understand each other better to easily communicate at work.

Thank You