

High Temperature Response

Alarm Threshold

90°C

Possible Causes

- Cooling failure
- Bearing wear
- Excessive friction
- Blocked cooling line

Operator Response

1. Reduce load.
2. Activate secondary cooling.
3. Inspect coolant flow.
4. Verify lubrication.

Maintenance

Replace damaged bearings.

Clean heat exchanger.

Restart after temperature drops below 75°C.