

High Vibration Investigation

Alarm

25 mm/s

Possible Causes

Bearing failure

Misalignment

Loose foundation

Rotor imbalance

Maintenance

Replace bearings.

Realign coupling.

Balance rotor.

Tighten anchor bolts.