

****Inspection Report****

Executive Summary

On July 19, 2026, our team conducted an inspection of steel surfaces at [Plant Name]. The inspection revealed a high percentage of patches on the surface, which compromised the overall quality of the material.

Technical Analysis

Detected Defects:

* Patches: 68.70%

The detected defects were categorized as patches due to their irregular shape and appearance. These patches are considered a significant concern as they can affect the strength and durability of the steel surface.

Severity Assessment

****High****

Due to the high percentage of patches, it is deemed that the inspection has revealed a critical issue with the material quality. Immediate attention is required to rectify this defect.

Recommended Actions

1. ****Re-inspection and Verification****: Conduct an additional re-inspection of the steel surface to verify the extent of the patches and ensure that no similar defects are missed.
2. ****Material Re-testing****: Perform further testing on the material to determine its mechanical properties and strength, ensuring compliance with industry standards.
3. ****Process Control Adjustments****: Review and adjust production processes to prevent the occurrence of such defects in future productions.

Final Recommendation

****NEEDS REVIEW****

Due to the high percentage of patches detected, further review and evaluation are necessary before giving a final assessment on the material's quality.