

Synthetic Condition Observation Memo

This PDF is intended only for local upload testing in LuxRenovate Intelligence. It does not describe a real client project.

Building context:

- Older residential building under renovation consideration.
- Approximate address and commune are known through the demo site context.
- Current condition has not been verified by a full engineering inspection.

Available evidence:

- Owner reports prior roof repair, but no technical report is attached.
- No complete as-built drawings are available.
- No structural calculations are available.
- No fire-safety approval dossier is available.

Observed Items For Human Review

1. Basement humidity

Moisture marks were reportedly visible near the basement wall after heavy rainfall. A dedicated humidity assessment is recommended before renovation planning.

2. Facade and openings

Minor cracks were mentioned near window openings. These observations require a site inspection and should not be interpreted as a structural diagnosis.

3. MEP systems

Electrical and heating systems appear dated based on owner notes. Maintenance records and technical documentation should be requested.

4. Hazardous materials

No asbestos or hazardous-material survey was provided. This gap should be resolved before intrusive works.