

Scanned Owner Note For OCR Testing

This page is intentionally embedded as an image only. It has no PDF text layer.

Reported renovation preparation gaps:

- No structural drawings are available.
- No fire-safety dossier was provided.
- Basement humidity was observed after heavy rain.
- Electrical and heating systems appear dated.
- Hazardous-material survey is missing.

Recommended human review:

- Structural walkthrough before load-bearing changes.
- Humidity assessment in basement areas.
- MEP documentation review.
- Hazardous-material screening before intrusive works.