


Control only moves down the ladder: Tier 1, then Tier 2, then Tier 3. Every path to the motors passes through Tier 3.
Targets, to be measured: command freshness 50 ms, watchdogs 20 ms, 1 kHz tick, clamp under 10 µs.