-		EVENT ANALYSIS REPORT							
	UNIT NO: 03	TPS: Khaperk	Unit Capa		nit Capacity : 2	city: 210 MW			
	1. *HO Code :	Station Code: TO	.00	Time -		Date -		No. of Days from last sync. :	
	1. Ho code :	Station Code: T003		19:15 Hrs	13	3/05/2015	04	04 days	
	2. Operating conditions at the time of Event :-								
	Loa	Load		Coal Cycles in service			Oil Support		
	68 MW			В,С				CD elevation	
	3. Nature of Event: T.A. Set withdrawn for attending HPT balancing leakoff line leakages.								
	4. Name of First Up , Main Protections & Protection on which GCB tripped :								
	Turbine Tripped (First Up), Generator Protection Operated, Gen Class – A trip.								
	5A) Observations: NIL								
	5B) Remedial Action/work done : - TM : Balancing Leak-Off line welding carried out, insulation done.								
	6. Root Cause Anal	oot Cause Analysis:							
T.A. Set withdrawn for attending HPT balancing leakoff line leakages.									
	7. Preventive action	Preventive action suggested (Short Term):-							
	8. Preventive action suggested (Long Term) :-								
	9. Similar event occurred last time:-			U - 3, 210 MW Time-		ie-		Date:	
ŀ	Event: No Similar Event Found								
-	9A. Implementation Status of Long Term/Short Term measures stated at Sr. No 7 & 8 :-								
-	10. Boiler lighted	,	Time - 05:55 Hrs			Date-14/05/2015			
ŀ	11. T-A Set Synchronized			Time - 09:15 Hrs			Date- 14/05/2015		
12. Remark :-									
-									
	Aralla								
								Chief Engineer	
	1. Procurement/Re	Replacement Plan:							
2. Operational Error: 3. Delay in Maintenance: 4. Delay in bringing back the Unit: 5. Training of Staff:									
L	6. Whether remedi	al action is comple	eted satis	sfactory & point is	s clos	ed:			
	C E/Dy C E (Works)								