UNIT NO: 04 1.*HO Code:		EVENTAN	IALYSIS REPORT			
1 *UO Codo :	TPS: Khaperkh	eda TPS	Unit Capacity : 210 MW			
1. HO Code :	Station Code: T003	Time – 22:57 Hrs	Date - 21/12/2017		No. of days from last sync. : 5 days	
2. Operating co	nditions at the tim		ades rec			
Load		-	Coal Cycles in service		Oil Support	
160 MW		A, B, C, E & F			NIL	
3. Nature of Eve	ent: TA set tripped du	e to "Furnace Pres	ssure Very High".			,
	t Up , Main Protectio ure Very High (First L		-	_	ay Operated.	
5A) Observation (Coal Cycle-I Pressure Ve	ns: On dt. 22/12/201 O Standby). Due to fall ry High" protection. S Action/work done: N	7 at 22:57 hrs. Uni ling of clinker, furn et tripped on boile	t-4 was sharing 16 nace pressure distu er interlock. GCB op	0 MW lo	ad with five co	d on "Furnace
high' protection. Preventive ac	nalysis: Due to falling on. tion suggested (Sho	rt Term):	e draft disturbed ar	nd boiler	tripped on 'fu	rnace pressure very
9. Similar event occurred last time : Event: T.A. Set tripped on "Furnace Pressure			Unit No # 4 , 210 MW		:: 22:42 Hrs.	Date:15/12/2017
	ns: No specific work		•			
	tion Status of Long T	Term/Short Term	n measures stated	at Sir N	o 7 & 8 :-	
10. Boiler lighted up		Time	Time - 23:30Hrs		Date - 21/12/2017	
11. T-A Set Synchronized		Time	- 02:30 Hrs		Date - 22/12/2017	
12. Remark:						D
			,			Chief Engineer
13. Recommend	ations of Works Sec	tion:				Chief Engineer
						Chief Engineer
1. Procuren	nent/Replacement P					Chief Engineer
1. Procuren 2. Operation	nent/Replacement P nal Error:					Chief Engineer
1. Procuren 2. Operation 3. Delay in M	nent/Replacement P nal Error': Maintenance:	lan:				Chief Engineer
1. Procuren 2. Operation 3. Delay in N 4. Delay in N	nent/Replacement P nal Error: Maintenance: oringing back the Un	lan:				Chief Engineer
1. Procuren 2. Operation 3. Delay in N 4. Delay in N 5. Training	nent/Replacement P nal Error: Maintenance: oringing back the Un	rlan: uit:	rtory & point is cla	osed		Chief Engineer