EVENT ANALYSIS REPORT								
UNIT NO: 04	TPS: Khaperkhe	da TPS Unit Capacit			acity	y: 210 MW		
1. *HO Code : Station Code :		Time -				No. of days from last sync.:		
T003 09:21 Hrs 04/03/2018 5 days								
2. Operating conditions at the time of Event :- Load Coal Cycles in service Oil Support								
101 MW		B & C				NIL .		
3. Nature of Event: Unit withdrawn as per directives of ED (0&M).								
4. Name of First Up, Main Protections & Protection on which GCB tripped:								
Flame Failure (First Up), MFT, Turbine Tripped, Generator Class 'A', Loss Of All Fuel. 5 A) Observations: On Dt. 04/03/2018 at 08:30 hrs. set was on load 160 MW load with five C/c in service (F-s/by).								
load was reduced by withdrawing C/c one by one, set tripped on 'Flame Failure'.								
5 B) Remedial Action/work done: No work carried out.								
6. Root Cause Analysis: As per directives of ED (0&M) Khaperkheda U-4 is to be withdrawn as Koridi U-9 is synchronized so as to maintain total DC.								
7. Preventive action suggested (Short Term):								
8. Preventive action suggested (Long Term):								
9. Similar event occurred last time :			Unit No # 4 , 210 MW			Time:	Date:	
Event: No similar event found.								
Remedial Actions:								
9A. Implementation Status of Long Term/Short Term measures stated at Sr No 7 & 8:-								
10. Boiler lighted up			Time – 23:35 Hrs		Date - 06/03/2018			
11. T-A Set Synchronized			Time - 09:16 Hrs			Date - 07/03/2018		
12. Remark:								
							100	
							ChiefFeeine	
Chief Engineer 13. Recommendations of Works Section :								
1. Procurement/Replacement Plan:								
2. Operational Error:								
3. Delay in Maintenance:								
4. Delay in bringing back the Unit:								
	5. Training of Staff:							
6. Whether remedial action is completed satisfactory & point is closed:								

C E/Dy C E (Works)