		ACTION OF THE PROPERTY OF THE	ALYSIS REPORT		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
UNIT NO: 02	TPS: Khaperkh	eda TPS	Unit Capacity : 210 MW			
1. *HO Code :	Station Code : T003	Time - 01:55 Hrs	Date -08/09/201	7	s from last sync. : 31 days	
2. Operating con	ditions at the time	of Event:				
Load		Coal Cyc	Coal Cycles in service		Oil Support	
16 MW			Е		AB*2, CD*3	
3. Nature of Even	t: TA set tripped on	drum level v. high pr	otection.	•		
Drum Level Very Operated, AVR 5 A) Observations	High(First Up),Gene PT Fuse Fail. s: On dt.08/09/201	erator Protection on which are the Protection Operator Protection	erated, Turbine Trip	, NCF occur at C/M	B, D & F.(C/M A PBL,	
, , ,		54°C, Reheater Tem	p-444/454°C, Drum	Level +226 mmwc.		
	tion/work done: No a	20				
6. Root Cause Ana	alysis: Due to NCF occ	ur at C/M B, D & F tem	perature inside the	furnace reduced an	d set tripped on	
drum level very	high protection.					
7. Preventive acti	on suggested (Short	Term):				
8. Preventive acti	on suggested (Long	Term):				
9. Similar event occurred last time :		Unit M	No #2, 210 MW	Time: hrs	Date :	
Event: No simila	ar event found.	I		я		
Remedial Actions						
9A. Implementati	on Status of Long Te	rm/Short Term meas	ures stated at Sr No	7 & 8:-		
10. Boiler lighted up		Time - 0	06:35 Hrs.	Date - 08/09	Date - 08/09/2017	
11. T-A Set Synchronized		Time -	10:07 Hrs.	Date - 08/09	Date - 08/09/2017	
12. Remark:		l		' ⊗	Chief Engineer	
	tions of Works Section					
	nent/Replacement	Plan:				
2. Operatio	nal Error:		R			
3. Delay in	Maintenance:					
4. Delay in	bringing back the U	Jnit:				
5. Training	of Staff:		-			
6. Whether	remedial action is	completed satisfac	tory & point is clos	ed:		