Useful formulae

Peak Time

$$T_p = \frac{\pi}{\omega_n \sqrt{1 - \zeta^2}}$$

Percent Overshoot

$$PO = 100 \exp\left(\frac{-\pi\zeta}{\sqrt{1-\zeta^2}}\right)$$

Settling Time

$$T=rac{1}{\zeta\omega_n}, \qquad T_s=4T$$

Second-Order Transfer Function

$$G(s) = \frac{K\omega_n^2}{s^2 + 2\zeta\omega_n s + \omega_n^2}$$

Steady-State Error

$$e_{ss} = \lim_{s \to 0} sE(s) = \lim_{s \to 0} sR(s) \left(1 - \frac{C(s)}{R(s)}\right) = \lim_{s \to 0} \frac{sR(s)}{1 + G(s)}$$

PID Controller

$$G_c = K_p + \frac{K_i}{S} + K_d S = K_p \left(1 + \frac{1}{T_i S} + T_d S \right)$$

Nyquist Stability Criterion

$$N = P - Z$$

Eigenvalues

$$\det(A - \lambda I) = 0$$

Root Locus Rules:

Rule 4 – the number of asymptotes is the number of OL poles minus the number of OL zeros

Rule 5 – the angle of the asymptotes is given by $\alpha = \frac{\pm (2i+1)180}{n-m}$

Rule 6 – the intersection of the asymptotes with the real axis is given by $\rho_0 = \frac{(sum\ of\ OL\ poles) - (sum\ of\ OL\ zeros)}{n-m}$

Rule 7 – loci are symmetrical with respect to the real axis
Rule 8 – sections of the real axis that are to the left of an odd

total number of OL poles and zeros on this axis form part of the loci

Rule 9 – points of breakaway or arrival at the real axis may exist.

Routh-Hurwitz:

For a generic characteristic equation of the form:

$$a_n s^n + a_{n-1} s^{n-1} + \dots + a_1 s + a_0 = 0$$

The Routh array is constructed as follows:

$$s^{n}$$
 a_{n} a_{n-2} a_{n-4} \cdots 0 s^{n-1} a_{n-1} a_{n-3} a_{n-5} \cdots 0 s^{n-2} b_{1} b_{2} b_{3} \cdots 0 s^{n-3} c_{1} c_{2} c_{3} \cdots 0 \vdots s^{1} g_{1} 0 s^{0} h_{1} 0

$$b_{1} = \frac{-1}{a_{n-1}} \begin{vmatrix} a_{n} & a_{n-2} \\ a_{n-1} & a_{n-3} \end{vmatrix} = \frac{1}{a_{n-1}} (a_{n-1}a_{n-2} - a_{n}a_{n-3})$$

$$b_{2} = \frac{-1}{a_{n-1}} \begin{vmatrix} a_{n} & a_{n-4} \\ a_{n-1} & a_{n-5} \end{vmatrix} = \frac{1}{a_{n-1}} (a_{n-1}a_{n-4} - a_{n}a_{n-5})$$

$$b_{3} = \frac{-1}{a_{n-1}} \begin{vmatrix} a_{n} & a_{n-6} \\ a_{n-1} & a_{n-7} \end{vmatrix} = \frac{1}{a_{n-1}} (a_{n-1}a_{n-6} - a_{n}a_{n-7})$$

$$b_{1} = \frac{-1}{a_{n-1}} \begin{vmatrix} a_{n-1} & a_{n-3} \\ b_{1} & b_{2} \end{vmatrix} = \frac{1}{b_{1}} (b_{1}a_{n-3} - b_{2}a_{n-1})$$

$$b_{1} = \frac{-1}{a_{n-1}} \begin{vmatrix} a_{n-1} & a_{n-5} \\ b_{1} & b_{3} \end{vmatrix} = \frac{1}{b_{1}} (b_{1}a_{n-5} - b_{3}a_{n-1})$$

Observability – system is fully observable if following matrix is full-rank:

$$O = \begin{bmatrix} C \\ CA \\ CA^2 \end{bmatrix}$$

Controllability – system is fully controllable if following matrix is full-rank:

$$C = \begin{bmatrix} B & AB & A^2B \end{bmatrix}$$

Determinant of a 3-by-3 matrix:

$$A = \begin{bmatrix} a & b & c \\ d & e & f \\ g & h & i \end{bmatrix}$$
$$|A| = a \begin{vmatrix} e & f \\ h & i \end{vmatrix} - d \begin{vmatrix} b & c \\ h & i \end{vmatrix} + g \begin{vmatrix} b & c \\ e & f \end{vmatrix}$$

$$|A| = a(ei - fh) - d(bi - ch) + g(bf - ce)$$