

4-2-2 Take CP2000 as Example

The followings are abbreviations of different types of motors,

- IM: Induction motor
- PM: Permanent magnet synchronous AC motor
- IPM: Interior permanent magnet synchronous AC motor
- SPM: Surface permanent magnet synchronous AC motor
- SynRM: Synchronous reluctance motor

4-2-2-1 Permanent Magnet Motor Space Vector Control (PM SVC) Pr.00-11 = 2

- PMSVC Control Diagram

