;Write a program that will count up from 00 to FF at port A. Be sure to use PCHL command.

**MVI A,00H** 

L1: OUT 40H CPI 0FFH INR A JNC L2

L2: JZ L3 JMP L1

;Output is at O/P port 40H

L3: HLT