;Change the program in assignment 8 to display 80H if the bit is 1 else nothing.

MVI A,80H

STC

CMC

RAL;D5

RAL ;Rotating 3 times so that it comes at palce of carry

RAL

JNC IS_LOW; If D5 is low carry is low

MVI A,01H OUT 40H

IS_LOW: HLT

HLT