;Convert the problem no 4 for the 16-bit numbers.

.MODEL SMALL
.DATA
.CODE

MOV DX,0000H MOV BX,0200H MOV CL,00H

MOV [BX],08H ;Put your 1st number LSB here MOV [BX+01H],0DH ;Put your 1st number MSB here MOV [BX+02H],62H ;Put your 2nd number LSB here MOV [BX+03H],05H ;Put your 2nd number MSB here MOV [BX+04],08H ;Put your 3rd number LSB here MOV [BX+05H],0BH ;Put your 3rd number MSB here MOV [BX+06H],8DH ;Put your 4th number LSB here MOV [BX+07H],0E2H ;Put your 4th number MSB here

MOV AL,[BX]
MOV AH,[BX+01H]
MOV CL,[BX+02H]
MOV CH,[BX+03H]
ADD AL,CL
ADC AH,CH

MOV CL,[BX+04H] MOV CH,[BX+05H] ADD AL,CL ADC AH,CH

MOV CL,[BX+06H] MOV CH,[BX+07H] ADD AL,CL ADC AH,CH MOV [BX+08H],AL MOV [BX+09H],AH

MOV AH,4CH INT 21H

**END**