;Write a program that will count up from 00 to FF at port A. Be sure to use PCHL command.

MVI A,00H

L1: OUT 40H

INR A JZ L2

LXI H,L1 PCHL

L2: HLT

;Write a program that will count up from 00 to FF at port A. Be sure to use PCHL command.

MVI A,00H

L1: OUT 40H CPI 0FFH INR A JNC L2

L2: JZ L3 JMP L1

;Output is at O/P port 40H

L3: HLT