;Write a program to add nos. from one to fifty and display the 16 bit result at port A & B.

LXI H,00H LXI B,00H

L1: DAD B INR C MOV A,C CPI 33H JNC L2

L2: JZ L3
JMP L1
;Result is at HL

L3: MOV A,L OUT 40H MOV A,H OUT 41H HLT