




MicroScout ToF side satellite – VL53L1X satellite

XSHUT has a 10 k pull-DOWN here instead of the datasheet's pull-up: the sensor stays in reset until firmware releases it, which the boot-time re-addressing needs (all VL53L1X start at 0x29). GPIO1 interrupt not used.

I2C pull-ups are on the FC board only. 3 boards fitted: left, right, rear.



Size: A3	Date: 2026-10-09	Rev: G2-draft-1
KiCad E.D.A.	kiCad-cli 7.0.11+dfsg-1build4	Id: 2/2