ATmega48P/88P/168P/328P

Problem Fix/ Workaround

None

32.4.3 Rev A

- Unstable 32 kHz Oscillator
- 1. Unstable 32 kHz Oscillator

The 32 kHz oscillator does not work as system clock.

The 32 kHz oscillator used as asynchronous timer is inaccurate.

Problem Fix/ Workaround

None

