
(a) Speed ripple per setting
Speed ripple, std at steady state (RPM)
Setting (dashed line = baseline)
(b) Flatter PWM vs steadier speed
Speed ripple, std (RPM) ↓ steadier speed
PWM jitter (% duty) ← flatter command