Facilities requests

Ref	Description	Owner	Cost
F-101	Replace lobby carpet tiles and reseal the entrance mat well	Facilities	1,240.00
F-102	Repaint stairwell B	Building services team	860.50
F-103	Service rooftop HVAC units before the summer peak	External contractor	4,310.75
F-104	Fix badge reader at loading dock	Security	295.00