

PT. SURYA SEGARAy marine

- AUTHORIZED SERVICE STATION ILR, LIFEBOAT, DAVIT LAUNCHING APPLIANCE
- Fire Extinguisher, CO2 Fix System Service and Safety Equipment Supply

Head Office: Jl. Perak Timur 358 Surabaya - Indonesia, Telp. +62 31 3292021, 3292022 Fax. +62 31 3291423 APPROVAL: SAI GLOBAL ISO 9001, ABS, LLOYD'S REGISTER, DNV-GL, NKK, BTKP, BKI | www.suryasegara.com

CERTIFICATE

of Inspection

	07	09	GAS NURI ARIZONA	IND	Flag: ONESIA	9113927	SS-210704.2.5
Place of service : Classification Society KALBUT - INDONESIA KOREA				Enclosed:			
		and tester	hat the systems and equipment d according to requirement from y of equipment and working co	n IMO reg	ulation, SOLAS	and manufacture	
Ę	-	Fixed C	CO2 System	×	Medical Oxygen		
	-,	Fixed F	oam System		Breathing Apparatus		
	,=X	Foam T	est Analist	-	Escape Sets		
	-	Fixed H	Ialon System	-	Rubber Boat		
	-	Fixed D	Ory Powder System		Life Jacket		
	-	Portable	e Fire Extinguisher		Summary of Actions		



PT. SURYA SEGARAy marine

- AUTHORIZED SERVICE STATION ILR, LIFEBOAT, DAVIT LAUNCHING APPLIANCE
- · Fire Extinguisher, CO2 Fix System Service and Safety Equipment Supply

Head Office: Jl. Perak Timur 358 Surabaya - Indonesia, Telp. +62 31 3292021, 3292022 Fax. +62 31 3291423 APPROVAL: SAI GLOBAL ISO 9001, ABS, LLOYD'S REGISTER, DNV-GL, NKK, BTKP, BKI | www.suryasegara.com

MEDICAL OXYGEN SERVICE REPORT

Page: 1 of 1

Year	Month	Day	Type and name of ship/unit:	IMO No. :	Certificate No. :
2021	07	09	GAS NURI ARIZONA	9113927	SS-210704.2.5

Description of working codes:

1 = Inspection

2 = Refilling

3 = Hydrostatic test

4 = Repaired

5 = Repainted

6 = New Supply

7 = Service

8 = Rejected

9 = Check Weight

10 = Check Content

No.	Cylinder Number	Capacity	Latest Hydrotest	Tested Pressure	Refilled Pressure	Workdone
1	09869	2,2 Ltr	04 - 2015	250 Bar	150 Bar	1,10
2	46942	2,2 Ltr	04 - 2015	250 Bar	150 Bar	1,10
3	46947	2,2 Ltr	04 - 2015	250 Bar	150 Bar	1, 10
4	10095	2,2 Ltr	04 - 2015	250 Bar	150 Bar	1, 10
5	6327753	- 40 Ltr	01 - 2015	300 Bar	200 Bar	1,10

This medical pagen requires service 12 month from the latest inspection.

SUBARI 7